



PENNOCK CREEK FLOODPLAIN MAPPING UPDATE STUDY GENERAL REPORT

DRAFT REV B

KGS Group 18-3065-003 March 2020

PREPARED BY:

Chen Jin, P.Eng. Water Resources Engineer

APPROVED BY:

Fuad Curi, P.Eng. Water Resources Department Head

TABLE OF CONTENTS

	EMENT OF LIMITATIONS AND CONDITIONS	
THIRD	D PARTY USE OF REPORT	iii
1.0	INTRODUCTION	1
	1.1 OBJECTIVES OF THE STUDY	1
	1.2 CRITERIA FOR FLOODPLAIN AND FILL LINE	
	1.3 GENERAL DESCRIPTION OF WATERSHED AND STUDY AREA	3
	1.4 HISTOY OF FLOODING	
	1.5 PREVIOUS STUDIES	
2.0	DATA USED IN THE ANALYSIS	
	2.1 LIDAR AND TOPOGRAPHIC DATA	
3.0	HYDROLOGIC ANALYSES	8
4.0	HYDRAULIC ANALYSIS	
5.0	FLOOD AND FILL LINE MAPPING	15
6.0	STUDY RESULTS AND COMPARISON WITH PREVIOUS FLOODPLAIN MAPS	16
	6.1 SPILL AREAS AND FLOOD VULNERABLE LOCATIONS	17
7.0	SUMMARY AND CONCLUSIONS	
	7.1 PROJECT SUMMARY	21
	7.2 RECOMMENDATIONS	22
8.0	REFERENCES	

TABLES FIGURES APPENDICES





LIST OF TABLES

- 1. LiDAR Acquisition Specifications
- 2. Hydrologic Characteristics Pennock Creek Watershed (From OFAT III)
- 3. Regional Frequency Analyses for the Pennock Creek Watershed
- 4. Recommended Pennock Creek Peak Flows at the Location of Confluence with Neebing River
- 5. Hydraulic Model Input Flows and Locations
- 6. Quantity of Flood Affected Infrastructure for All Floods

LIST OF FIGURES

- 1. Pennock Creek Reaches
- 2. Affected Infrastructure Regional Storm Flood

LIST OF APPENDICES

A. Infrastructure Located within the Flood Hazard Limit



STATEMENT OF LIMITATIONS AND CONDITIONS

THIRD PARTY USE OF REPORT

This report has been prepared for the Lakehead Region Conservation Authority, to whom this report has been addressed, and any use a third party makes of this report, or any reliance on or decisions made based on it, are the responsibility of such third parties. KGS Group accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions undertaken based on this report.



1.0 INTRODUCTION

1.1 OBJECTIVES OF THE STUDY

This study was commissioned to KGS Group by the Lakehead Region Conservation Authority (LRCA), with the objective of updating the existing floodplain mapping of Pennock Creek and its tributaries within the City of Thunder Bay and the Municipality of Oliver Paipoonge. The study included:

- The collection and processing of topographic data using LiDAR technology and ground surveys, as well as bathymetric data for the creek and tributaries.
- The preparation of mapping base data, including the development of a digital elevation model (DEM) with the topographic data obtained.
- Hydrologic analysis and modelling to obtain flows for representative flood events along the Pennock Creek system.
- Hydraulic analysis and modelling to calculate the conditions (water levels and flow velocities) across the creek system, associated with the flows estimated for the various flood events.
- The preparation of floodplain maps depicting the flood hazard limits and the administrative fill lines along the reaches of Pennock Creek and its tributaries included in the scope of project.
- The presentation of the study results to stakeholders and to the public in an open house, which will take place in March 2020.

Separate technical reports have been submitted to describe, in detail, the data used, the methodology applied, and the results obtained during the execution of the project. These reports include:

- Pennock Creek Floodplain Mapping and Kaministiquia River Floodplain Mapping Study LiDAR Report (KGS Group, 2019a).
- Pennock Creek Floodplain Mapping Update Study, Hydrologic Report (KGS Group, 2019b).
- Pennock Creek Floodplain Mapping Update Study, Hydraulics Report (KGS Group, 2019c).



This report provides a summary of the findings of the study described in the above noted technical reports.

1.2 CRITERIA FOR FLOODPLAIN AND FILL LINE

To minimize the risk of flooding to people and property, the Province of Ontario has established policies and flood standards to restrict development within floodplains.

The Lakehead Region is located within Zone 3, as defined in the Technical Guide – River and Stream Systems: Flooding Hazard Limit (Technical Guide, OMNR, 2002)¹. For all watersheds within this zone, the flooding hazard limit is defined as the greater of the flood resulting from:

- a. the Regional Storm (which for this area is the Timmins Storm of 1961), transposed and centred over the watershed and combined with the local conditions;
- b. the 100-Year flood;
- c. a flood which is greater than a) or b), which was actually experienced on a particular watershed or portion thereof, for example as a result of ice jams, and which has been approved as the standard for that specific area by the Minister of Natural Resources.

No specific storm, with the characteristics indicated in item "c", has been approved by the MNRF for the study area, so the criterion used in this study corresponds to the maximum from the conditions described in items "a" and "b".

The definition of the fill line, for administrative purposes, was based on the "Guidelines for Developing Schedules of Regulated Areas" (2006). The criteria described in that document includes consideration of the river valley characteristics and in particular stability of the bank slopes. LRCA indicated that, for this watershed, bank slopes with a horizontal to vertical ratio of 2:1 or greater are considered stable. The criteria for definition of the fill line applied for the Pennock Creek mapping can be summarized as follows:

¹ The Ministry of Natural Resources and Forestry (MNRF) was named Ontario Ministry of Natural Resources (OMNR) aat the time of release of the guidelines, Technical Guide – River and Stream Systems: Flooding Hazard Limit.



- In areas with gradual banks at the contact of the flood line with the terrain (bank slope flatter than 2H:1V), the fill line was set 15 m from the flood hazard line.
- In areas where a defined river bank was present, and the bank slope was flatter than 2H:1V, the fill line was set 15 m from the top of the bank.
- In areas with steep banks at the contact of the flood line with the terrain (bank slope equal or steeper than 2H:1V), the fill line was set 15 m from the point where the projection, from the floodline, of a 2H:1V slope would daylight.

1.3 GENERAL DESCRIPTION OF WATERSHED AND STUDY AREA


The Pennock Creek watershed is shown in Figure 1. The creek is a major tributary of the Neebing River. It originates north of the Village of Murillo in the Municipality of Oliver Paipoonge, and runs generally in the easterly direction, to flow into the Neebing River at a location near the Thunder Bay International Airport. The main branch of the creek is approximately 17.6 km long and its channel width is typically 5 to 8 m. The drainage area of this watershed is approximately 50 km².

The labelling system shown in Figure 1 was also used to identify the river branches and tributaries in the hydraulic model prepared as part of this study. In Figure 1, the main branch of Pennock Creek has been labelled as "P". The labels assigned to the tributaries of Pennock Creek include the letter "T" and a number indicating the order in which they join the creek. The ordering numbers were assigned in the direction from downstream to upstream. There are also a few second order tributaries, which are identified by the name given to the tributary that they join, followed by a dot and a consecutive number.

It must be noted that there are numerous small tributaries in the watershed that are not included in Figure 1. It was indicated by LRCA, that only the tributaries with draining areas larger than 125 ha were to be included in the hydraulic model.







Lakehead Region Conservation Authority Pennock Creek Floodplain Mapping Update General Report – Draft

1.4 HISTOY OF FLOODING

Hydrometric data records are not available for Pennock Creek and records or observations of historical flooding events are limited. LRCA provided photos at various locations of Pennock Creek taken during the flood events that occurred on May 28, 2012. These photos were used as references to compare with results from the hydraulic model prepared as part of this study, details were discussed in the hydraulic technical report (KGS, 2019c).

1.5 **PREVIOUS STUDIES**

There is a previous study for the Pennock Creek watershed, that was carried out for the purpose of floodplain mapping. It was completed in 1982 by M.M. Dillon Limited (Dillon), and included hydrologic analyses and hydraulic modelling. The peak flow obtained in that study for the Regional Storm, and used as the basis for the previous floodplain maps, was found in this study to be proportionally too large. This is further discussed in Section 3.0.



2.0 DATA USED IN THE ANALYSIS

2.1 LIDAR AND TOPOGRAPHIC DATA

The topographic data used in this study is referenced to the 6-degree Universal Transverse Mercator (UTM), North American Datum 1983 (NAD83CSRS) Zone 16 grid projection system and Canadian Geodetic Vertical Datum (CGVD28).

As part of the study, LiDAR (Light Detection and Ranging) data along Pennock Creek was obtained by KGS Group and its sub-consultant ATLIS Geomatics. LiDAR and aerial imagery acquisition were completed by ATLIS on May 17th and 18th 2019. The data capturing, processing, and quality control are reported in the Pennock Creek Floodplain Mapping and Kaministiquia River Floodplain Mapping Study LiDAR Project Report by KGS (2019a). The specifications of the LiDAR capture are summarized in Table 1.

LiDAR Acquisition Specifica	tions
Flying Height (metres AGL)	805 to 1100m
Aircraft Ground Speed (knots)	105
Pulse Rate (KHz)	482
Scan Rate (Hz)	47
Full Field of View (degrees)	40
Multi-Pulse	YES
Nominal Swath Width (Metres)	1025
Swath Overlap (percentage)	30%
Nominal Point Spacing Across Track (Metres)	0.3
Nominal Point Spacing Along Track (Metres)	0.3
Average Pulse Density (points per m ²)	8.7
Vertical Accuracy	5 cm or less RMSE
Horizontal Accuracy	25 cm or less RMSE

TABLE 1 LIDAR ACQUISITION SPECIFICATIONS



Lakehead Region Conservation Authority Pennock Creek Floodplain Mapping Update General Report – Draft

Topographic surveys were carried out by KGS Group in October and November of 2018 and in May, June, and July of 2019. The surveys allowed developing a control network to support LiDAR acquisition, provide baseline coverage, and perform quality control on the LiDAR data. The LiDAR data was then used to develop a Digital Elevation Model (DEM) with the program Model Builder in ArcGIS v10.4. This DEM was the basis for the derivation of the cross sections used in this study for the preparation of the hydraulic model of Pennock Creek.

Topographic and bathymetric surveys were also carried out and used to supplement the LiDAR data. This work included localized survey of riverbed elevations, focused at the crossing locations. The data collected at the crossings also included measurements of the size and elevations of the water passages, top of road elevation as well as photo documentation. A total of 108 locations were surveyed of which 54 were included in the hydraulic model². The structures included in the model are six bridges, 47 culverts and one inline structure. Data sheets summarizing the data collected at all locations surveyed are provided in the hydraulic technical report (KGS, 2019c).

² A number of crossings that were survey corresponded to tributaries with small drainage areas (less than 125 ha). These tributaries were not included in the hydraulic model, as per the requirements specified for this study.



Lakehead Region Conservation Authority Pennock Creek Floodplain Mapping Update General Report – Draft

3.0 HYDROLOGIC ANALYSES

The drainage area of this watershed is approximately 50 km². It includes the main branch of Pennock Creek, as well as several smaller tributaries. The headwaters of the creek are located north of Oliver Road and are situated at approximately El. 289 m. The confluence with the Neebing River is located at approximately El. 188 m. Characteristic parameters of the Pennock Creek watershed, obtained using the MNRF's Ontario Flow Assessment Tool OFAT III³, are listed in Table 2.

TABLE 2 HYDROLOGIC CHARACTERISTICS PENNOCK CREEK WATERSHED (FROM OFAT III)⁴

Drainage Area	49.5 km²
Shape Factor	19.0
Mean Elevation	253.5 m
Maximum Elevation	363.3 m
Mean Slope	2.5 %
Length of Main Channel	30.7 km
Slope of Main Channel	5.5 %
Annual Mean Temperature	3.1 °C
Annual Precipitation	711 mm
Area of Lakes	0.143 km ²
Area of Wetlands	6.3 km ²

The existing land use in the Pennock Creek Watershed is predominantly rural, especially in Oliver Paipoonge. The watershed also includes some suburban developments and pockets of commercial, industrial and institutional land use in the villages of Murillo and Rosslyn, and in the City of Thunder Bay.

⁴ The drainage area shown in Table 1 was obtained with OFAT III. It is slightly less than what was measured independently with GIS tools.



³ The Ontario Flow Assessment Tool (OFAT), version 3, is an online spatially-based application which includes a number of tools that allow conducting hydrologic tasks. It was developed by the Ontario Ministry of Natural Resources and Forestry.

As part of this study, a hydrologic analysis of the Pennock Creek watershed was carried out by KGS Group and it was reported in the Hydrology Report KGS (2019b). It included Regional Flood Frequency Analysis and hydrologic modelling.

KGS carried out the Regional Flood Frequency Analyses (using the Index Flood Method) with the formulas developed in the McIntyre River Floodplain Mapping Study (HMM, 2015) and the McVicar Creek Floodplain Mapping Study (KGS, 2018). The two formulas provided similar results; but those obtained with the formula from the McIntyre River Study were slightly more conservative, and therefore were adopted in this study.

The Regional Flood Frequency Analysis was used to obtain peak flows for Pennock Creek, based on the single flood frequency flows obtained for the Neebing River at Water Survey Canada Station 02AB008, that had been obtained as part of the Neebing River Floodplain Mapping update (KGS, 2018). This is considered a correct approach given that Pennock Creek is a tributary of the Neebing River and the characteristics of those two watersheds are similar. The results were adopted in this study (KGS, 2019b) and are shown in Table 3.

Return Period	Index Flow Method Using Flood Frequency Values for the Neebing River
2	8.2
5	14.4
10	19.0
25	24.9
50	29.5
100	34.0

 TABLE 3

 REGIONAL FREQUENCY ANALYSES OF THE PENNOCK CREEK WATERSHED

The program Visual OTTHYMO Version 5.0 (VO 5) was used in this study to develop a hydrologic model of the Pennock Creek watershed. The model elements used to represent the various watershed features include sub-catchments, routing channels and reservoirs. The hydrologic model was developed based on the topographic data available as well as the characteristics of the various sub-catchments, obtained from OFAT III and from the Ontario Agricultural Information Atlas. The hydrologic model domain extended through the entire



Pennock Creek watershed, from the headwaters of its branches and tributaries to its mouth at the confluence with the Neebing River.

In the hydrologic model, the watershed was divided into 25 sub-catchments. Twenty-two subcatchments correspond to rural areas and three, to suburban catchments. The model also includes seventeen river reaches that allow simulating the routing of runoff flows as they travel through the river system. A review of the future development plans for the watershed indicated only minor changes to land use. It was, therefore, determined that the model prepared based on existing conditions also represented anticipated future conditions.

The model was validated, using the results obtained from the Regional Flood Frequency Analysis, and was used to simulate the runoff resulting from the Regional Storm Flood as well as from recurrent storms ranging from 2 to 100 years return period. The Regional Storm for the area is the Timmins Storm. Hyetographs for this storm were prepared for the Pennock Creek watershed using an area reduction factor of 84%. This factor was based on the equivalent circular area of the watershed in adherence with the Technical Guide (MNR, 2002). For the recurrent events, synthetic storm hyetographs were developed using the most current Intensity-Duration-Frequency curves for the City of Thunder Bay.

The results of the simulation of the Regional Storm Flood were considerably lower than those reported in Dillon's 1982 study and used in the previous floodplain maps for the Pennock Creek. The 1982 value (108.6 m³/s) is too high, considering that the peak flow obtained for the entire Neebing River watershed (which is approximately 4.5 times larger) was 128 m³/s (KGS, 2018)⁵. The two studies used different approaches, since modern hydrologic models were not available in 1982.

The values recommended to be adopted as representative of peak flood flows for Pennock Creek at the confluence with the Neebing River are listed in Table 4.

⁵ This value was adopted for the Neebing Floodplain Mapping Update because it had been used in the previous floodplain maps for the Neebing River and was only slightly greater than the value of 125 m³/s obtained with the new model prepared by KGS Group.



TABLE 4

RECOMMENDED PENNOCK CREEK PEAK FLOWS AT THE LOCATION OF CONFLUENCE WITH NEEBING RIVER

2-Year	5-Year	10-Year	25-Year	50-Year	100-Year	Regional Storm
8.2	14.4	19.0	24.9	29.5	34.1	52.4



4.0 HYDRAULIC ANALYSIS

The computer program HEC-RAS, Version 5.0.7, was used in this study to prepare a hydraulic model of the Pennock Creek system. The hydraulic model was used to simulate the recurrent events with return periods ranging from 2 to 100 years, as well as the Regional Storm Flood.

The model includes all the river reaches highlighted in Figure 1. Cross sections were extracted from the DEM and the localized survey data described in Section 2.1. These cross sections were spaced at maximum intervals of 200 m, and in most cases at shorter distances, particularly at locations of crossings and where the data suggested changes in the geometry of the channel.

The downstream boundary condition for the model was the water levels at the Neebing River, for the Regional Storm Flood and recurrent flood events, obtained from the Neebing River study (KGS, 2018). Input flows were provided at the upstream section of each river branch and tributary reach, based on the results from the hydrologic analysis (Section 3.0), so that the flows at the confluence with the Neebing River matched the values indicated in Table 4. The model inflows are summarized in Table 5.

The Manning n-values used in the model to represent surface roughness were selected based on typical values obtained in the literature for rivers and floodplains with similar characteristics (surface type, vegetation coverage) to those observed in aerial imagery and the photographs collected during the ground survey for the various reaches of Pennock Creek. In the lower reaches of the creek, where the main channel is generally clean and uniform, a Manning nvalue of 0.03 was adopted. In the upper Pennock Creek branches and tributaries, the channel features gravels, small cobbles and weeds on the riverbed, as well as sections of shallow flow, so a higher Manning n-value of 0.035 was adopted. For the overbanks, generally covered by grass and medium to dense brush and trees, the selected n-values ranged from 0.07 to 0.1; except at farmlands and residential lands, where the adopted Manning n-values were 0.04 and 0.05, and at road surfaces where an n-value of 0.025 was used.

The model includes the culverts, bridges and hydraulic structures surveyed in the study and described in Section 2.1.



Model Loc	ation	Figure 1			Flo	w (m³/s)			
Branch	Station (km)	Reference ID	Regional Flood	100 Year	50 Year	25 year	10 Year	5 Year	2 Year
Neebing_01	37.464	1	109.77	80.27	67.11	55.46	40.81	29.29	14.47
Neebing_02	37.571	2	109.77	80.27	67.11	55.46	40.81	29.29	14.47
P_01	1.737	3	52.41	34.14	29.53	24.9	19.01	14.35	8.16
P_01	2.589	4	52.25	34.07	29.46	24.85	18.97	14.33	8.15
P_01	6.759	5	51.74	33.84	29.13	24.58	18.78	14.19	8.09
P_01	9.824	6	48.34	32.16	27.28	23.05	17.68	13.42	7.72
P_01	11.629	7	44.63	29.72	25.28	21.43	16.53	12.62	7.39
P_02	1.317	8	31.61	21.02	17.88	15.15	11.68	8.91	5.2
P_03	0.137	9	26.96	17.79	15.14	12.82	9.87	7.51	4.36
P_04	2.453	13	24.57	16.16	13.75	11.63	8.95	6.81	3.94
P_05	0.802	14	16.95	11.02	9.35	7.89	6.04	4.57	2.61
P_06	4.203	15	12.74	8.47	7.19	6.08	4.66	3.53	2.02
P_06	5.658	16	8.9	5.85	4.97	4.21	3.23	2.45	1.41
P_06	6.987	17	7.72	5.2	4.43	3.75	2.88	2.19	1.26
P_06	7.458	18	5.98	4.1	3.48	2.95	2.26	1.72	0.99
T1_01	0.503	19	9.66	6.56	5.61	4.79	3.72	2.88	1.73
T1_02	1.214	22	7.15	4.82	4.11	3.5	2.71	2.09	1.24
T1_02	2.303	23	6.22	4.13	3.5	2.96	2.26	1.71	0.98
T1_02	4.883	24	4.87	3.28	2.79	2.36	1.81	1.37	0.78
T1_1.1	1.174	27	2.51	1.74	1.5	1.29	1.01	0.79	0.49
T2_01	2.808	31	2.39	1.63	1.39	1.18	0.92	0.71	0.42
T3_01	1.665	32	3.67	2.38	1.99	1.65	1.23	0.91	0.5
T3_02	2.164	33	0.7	0.41	0.33	0.26	0.18	0.12	0.05
T3_1.1	1.545	34	2.12	1.42	1.21	1.02	0.78	0.59	0.34
T4_01	1.447	35	5.76	3.96	3.39	2.89	2.26	1.75	1.04
T4_01	2.527	36	3.21	2.06	1.75	1.48	1.14	0.86	0.49
T5_01	1.442	37	4.48	2.86	2.42	2.04	1.56	1.18	0.67
T5_01	2.527	38	3.21	2.06	1.75	1.48	1.14	0.86	0.49
T5_01	3.894	39	1.76	1.14	0.97	0.82	0.63	0.48	0.28

TABLE 5 HYDRAULIC MODEL INPUT FLOWS AND LOCATIONS

There was no data for calibration or validation of the hydraulic model. The model results for the Regional Storm Flood were compared with the photos and observations obtained from the May 28, 2012 flood event, described in Section 1.2.



Lakehead Region Conservation Authority Pennock Creek Floodplain Mapping Update General Report – Draft

Recognizing the uncertainty associated to numerical modelling, sensitivity analyses were carried out to evaluate the effect of the Neebing River levels and the adopted roughness parameters. The results showed that the model results are largely independent of the assumptions made for these two parameters, within the range of values normally acceptable for the site conditions. The values adopted for the calibrated model are considered appropriate for the analysis to define flood hazard limits.

The adopted hydraulic model was used to simulate recurrent events corresponding to 2, 5, 10, 25, 50, and 100-Year return periods and the Regional Storm Flood.



Lakehead Region Conservation Authority Pennock Creek Floodplain Mapping Update General Report – Draft

5.0 FLOOD AND FILL LINE MAPPING

The proposed flood hazard limits for the Pennock Creek system are the water levels obtained from the simulation of the Timmins Storm, which is the Regional Storm for this watershed, and were higher than those obtained for the 100-Year event. These limits were plotted in floodplain maps that were prepared using a Geographic Information System (GIS). They were reviewed for consistency and adequacy by inspection of model results and terrain levels throughout the study area. Subsequently, the fill lines were generated based on the criteria described in Section 1.2 and refined after review and discussions with LRCA.

A set of floodplain maps were produced to display the flood hazard line and the fill line. The base mapping data for preparation of these maps includes:

- Imagery supplied by LRCA as part of the North West Ontario Orthophotography Project – 2017 (NWOOP), acquired through Land Information Ontario (LIO).
- Municipal boundaries, municipal parcels, and road network supplied by LRCA.
- Tile Index followed the City of Thunder Bay 1:2000 scale maps (1 km x 1 km) nonoverlapping tiles. The tile index data was provided by LRCA.
- 0.5 m and 1 m interval contours were developed from the LiDAR digital elevation model (DEM) by KGS Group.
- Cross sections, thalweg, and Regional Floodline were imported into GIS format from HEC-RAS by KGS Group.
- Fill line, prepared by KGS Group following the criteria described in Section 1.2.

The floodplain maps are included as an appendix in the Hydraulic Report (KGS Group, 2019c) and have been provided in digital copy format to LRCA. All floodplain maps are in 24x36 full size format.



6.0 STUDY RESULTS AND COMPARISON WITH PREVIOUS FLOODPLAIN MAPS

A general comparison of the results of the present study, with the previous flood lines provided by LRCA, show good agreement. In general, the present study shows less extensive flooding when compared to the previous study.

The following are locations where both the present study and the 1982 study show overbank flooding. These are described in detail in the hydraulic report (2019c).

- Upstream of the Thunder Lake Dam (Branch P_01), both the previous floodplain maps and the updated model results show spill over the private bridge off Rosslyn Road between 25th Side Rd. This area is shown in Map Sheet Number 355.
- At Hwy 130 (Branch P_01) both the previous floodplain maps and the updated model results show spill over the private bridge downstream of Hwy 130 on the main Pennock Creek channel; however, the 1982 floodplain maps show more extensive flooding upstream of Hwy 130. This area is shown in Map Sheet Number 354.
- At Cooper Road (Branch P_01) both the previous floodplain maps and the updated model results show overtopping of the private driveway off Cooper Road and another private pedestrian bridge to the west; but the 1982 floodplain maps show more extensive flooding. This area is shown in Map Sheet Number 353.
- At Vibert Road and Hwy 130 (Branch P_02, Tributary T3_01 and T2_01) both the previous floodplain maps and the updated model results show spill over Vibert Rd N and Vibert Rd, the ramp of Vibert Rd to Hwy 130 and Hwy 130. The updated model includes areas north of the Hwy 11 that had not been modeled in the previous study. This area is shown in Map Sheet Number 1960, 1961 and 1986.

The present study included major tributaries of Pennock Creek that were not included in the previous floodplain maps, and therefore it revealed locations of overtopping of banks and crossings that had not been previously identified. These are summarized below.

- North of Hwy 130 (Tributary T1_02 and T1_01), west to intersection with Cooper Rd, the updated model results indicate overtopping of one driveway and the road on the left river bank of reach T1_02. It also shows impact on two ancillary buildings in this area. This area is shown in Map Sheet Number 331 and 1961.
- Along Centre Street (Tributary T1_02), north of Pole line Rd, the updated model results show overtopping of three driveways those next to Centre Street, and also show impact on three ancillary buildings. This area is shown in Map Sheet Number 1886 and 1911.



- At Pole line Road (Tributary T4_01), east of intersection with Boulter Rd, the updated model results show overtopping of the Pole line Rd, one private crossing downstream of Pole line Road and another private crossing further downstream. This area is shown in Map Sheet Number 1909.
- At Pole line Road (Tributary T5_01), west of intersection with Fraser Rd, the results show overtopping of the Pole line Rd, and two private crossings off Pole line Road. This area is shown in Map Sheet Number 1908.
- At Wing Road (Branch P_06), the updated model results show spill over Wing Road, three private driveways off Wing Road, and a private pedestrian bridge east of Wing Road. This area is shown in Map Sheet Number 1907 and 1932.
- At Pole line Road (Branch P_06), east of Mud Lake Rd, the updated model results show overtopping of Pole line Rd and one private crossing south of it. This area is shown in Map Sheet Number 1906.
- At Mud Lake Rd (Branch P_06), north of Pole line Rd, the updated model results show spill over two crossings of Mud Lake Rd over the Pennock creek. This area is shown in Map Sheet Number 1880.
- At McLean Rd (Branch P_06), north of intersection with Baxendale Dr, the updated model results show spill over McLean Rd. This area is shown in Map Sheet Number 1856.
- At Baxendale Dr (Branch P_06), the updated model results show spill over Baxendale Dr and a driveway off Baxendale Dr. Spilling over the Baxendale Dr. also causes impact on additional four driveways south of Baxendale Dr. This area is shown in Map Sheet Number 1856.
- East of intersection of Oliver Rd ((Branch P_06) and Baxendale Dr., the updated model results indicate flooding one dwelling and eight ancillary buildings. This area is shown in Map Sheet Number 1856 and 1857.

6.1 SPILL AREAS AND FLOOD VULNERABLE LOCATIONS

Spill areas in Pennock Creek, identified in the analysis, include the areas along Vibert Rd, Vibert Rd N, Hwy 130, private road north of Hwy 130 (east of intersection with Cooper Rd), and Baxendale Dr.

The largest spill area in Pennock Creek, identified in the analysis, is around the intersection of Hwy 11, Hwy 130 (Arthur Rd) and Vibert Rd. This area is shown in in Appendix M and Map Sheet 1960 and 1961. The model results show that during the Regional Storm, the creek (Reaches P_04 and T2_01) would overtop the left river banks and spill over Vibert Rd N. These flood water would then discharge to the Tributary T1_1.1, at location north of Hwy 11.The



results also show that the creek (Reach P_02) would spill over Hwy 130 in direction from south to north. Another notable overtopping in this area, identified by the model results, is that Tributary T3_01 would overtop Vibert Rd (south of Hwy 11) then discharge to reach P_02. Overtopping in this area would cause flooding of Vibert Rd, Vibert Rd N, Hwy 130 and two private crossings.

In the same area, spills were also identified in the property of the Municipality of Oliver Paipoonge, as shown in Map 331. The analysis shows that the creek (Reaches T1_1.1 and T1_02) would overtop the road west of, and spills over to, this property. A review of the model results indicates that floodwaters will surround this building, but will not impact it since the building is located at higher land. Spills also appear to overtop of the driveway, north of the interception of Cooper Rd. and Hwy 130, flows into the open areas, and eventually discharge through the culvert at Hwy 130 and flow back to the river system. It is possible the spill will continue to the east further from the Hwy 130 culvert; however, the spill extent cannot be determined by this study.

Map 309 shows another notable spill, it discharges south to the open area as mentioned above. A review of the model results indicates that this spill will flow through the above discussed Hwy 130 culvert.

The model results also show spilling over Baxendale Dr at location west of Oliver Rd during the Regional Storm Flood, causing flooding of Baxendale Dr, driveway and private lot. This is shown in Map Sheet 1856.

A full list of areas with risk of flooding, not only for the Regional Storm but also for recurrent events is provided in Appendix A. The tables in that appendix show water depths, flow velocities and depth-velocity products obtained from the hydraulic model simulations. The tables highlight those areas where there could be potential risk to people and restrictions to access or egress, based on the criteria defined by LRCA. These criteria are based on MNR (2002) and consists of:





- flow depths in excess of 0.3 m,
- flow velocities in excess of 1.7 m/s, and
- depth velocity products in excess of 0.4 m2/s.

The features identified in Appendix A were classified in the following categories:

- Dwellings
- Ancillary buildings
- Lots
- Bridges/Culverts
- Roads
- Driveways

A summary of the number of affected infrastructures for all floods is provided in Table 6. The location of the features affected by the Regional Flood is summarized in Figure 2.


TABLE 6

QUANTITY OF FLOOD AFFECTED INFRASTRUCTURE FOR ALL FLOODS

				FLO		IITUDE		
		2-Year	5-Year	10- Year	25- Year	50- Year	100- Year	Regional
ED	Dwelling	0	0	0	0	0	0	0
L L L	Ancillary Building	0	0	1	3	4	4	9
	Lot	0	1	1	1	1	2	5
ST	Bridge/Culvert	1	5	5	8	10	10	10
ANTIT	Road	1	1	3	4	8	9	14
QUANT	Driveway	0	1	6	7	8	11	14







7.0 SUMMARY AND CONCLUSIONS

7.1 **PROJECT SUMMARY**

KGS Group was retained by the LRCA to update the floodplain mapping for the Pennock Creek system. A summary of the project tasks and findings is provided below:

- New LiDAR, topographic and bathymetric data was obtained for the Pennock Creek watershed and used to prepare a Digital Elevation Model (DEM) of the study area, in the municipality of Oliver Paipoonge and City of Thunder Bay. This new data satisfied the criteria for accuracy and density that was established in the terms of reference for the study.
- The topographic data used in this study is referenced to the 6-degree Universal Transverse Mercator (UTM), North American Datum 1983 (NAD83CSRS) Zone 16 grid projection system and Canadian Geodetic Vertical Datum (CGVD28).
- A Regional Flood Frequency Analysis was carried out with formulas prepared in the McIntyre River and McVicar Creek Floodplain Mapping studies. Results from both formulas are similar. The slightly higher results obtained with the formulas from the McIntyre River study were adopted in this study.
- Storm hyetographs for return periods ranging from 2 to 100 years, developed using the most current IDF curves for Thunder Bay were used in this study to obtain corresponding flows from the hydrologic model. The hyetographs were prepared using a Chicago Storm distribution. The storms were developed for a 24-hour duration with a peak occurring at 1/3 of the storm duration (r = 0.33). The 2 to 100 years storms were not simulated in the 1982 study.
- The Regional Storm for the area is the Timmins Storm. Hyetographs for this storm were prepared for the Pennock Creek watershed using an area reduction factor of 84%. This factor was based on the equivalent circular area of the watershed in adherence with the Technical Guide (MNR, 2002).
- A new hydrologic model was developed and validated with Regional Flood Frequency Analysis for Pennock Creek.
- The flows obtained with the hydrologic model for the Regional (Timmins) Storm Flood, were significantly lower than those obtained in Dillon (1982) and previously used for floodplain mapping. The differences are likely attributed to the use of different hydrologic calculation approaches. The values used in this study are considered to better represent the response of the watershed, and are consistent with the peak flows obtained for the Neebing River in a previous floodplain mapping study (KGS, 2018).
- A new hydraulic model was prepared with the program HEC-RAS for the Pennock Creek system, including the tributaries in the system that drained areas larger than 125 ha.



- The hydraulic model was used to simulate the hydraulic conditions during the Regional Storm Flood and recurrent flood events with return periods ranging from 2 to 100 years.
- Recognizing the uncertainty associated to numerical modelling, sensitivity analyses were carried out to evaluate the effect of the Neebing River levels and the adopted roughness parameters. The results showed that the model results are largely independent of the assumptions made for these two parameters, within the range of values normally acceptable for the site conditions. The values adopted for the calibrated model are considered appropriate for the analysis to define flood hazard limits.
- Floodplain maps were developed for the Pennock Creek based on the model results obtained for the Regional Storm Flood.
- A review of the updated floodplain maps, using this study report, indicates that in most parts the updated results were generally consistent with those previously obtained by Dillon (1982). However, the extent of the flooding obtained in the present study was less extensive.
- A review of the hydraulic model results was carried out to evaluate flow depth, velocity and depth-velocity product at the locations of buildings and infrastructure. These were compared with the hazard criteria required by LRCA. The results are listed for each building and infrastructure located within the flood hazard limit, in Appendix A.

7.2 RECOMMENDATIONS

Based on the investigations and analyses completed for this project, KGS Group has the following recommendations:

- Adopt the updated Pennock Creek floodplain maps that show the flood hazard limits in accordance with provincial regulations and the fill lines to be used for administrative purposes.
- Evaluate the available monitoring system and program in place with respect to the need to provide timely and adequate information to agencies and the public in the event of a flood in the Pennock Creek watershed. This evaluation could include a review of the local sources, the means to obtain and process the information from developing weather and flow forecasts, the tools (models, maps, tables) to forecast flood levels associated with the expected flows by using the hydraulic model, and the system to disseminate warning and execute emergency response actions.
- The table of locations of flood vulnerable infrastructure provided in Appendix A can be used for the prioritization of potential improvements to crossings that provide limited conveyance. This can be carried out through a technical study with terms of reference that would be developed with the information obtained in this study.



8.0 **REFERENCES**

- 1. M.M. Dillon Limited, 1982, Pennock Creek Flood Plain and Fill Line Mapping.
- 2. USACE, 2016, Hydraulic Reference Manual.
- 3. OMNR, 2002, Technical Guide River & Stream Systems: Flooding Hazard Limit.
- 4. MTO, 1997, Drainage Management Manual
- 5. USDA, 1986, Urban Hydrology for Small Watersheds Technical Release 55
- 6. KGS, 2018, Neebing River Floodplain Mapping Update Final Hydrologic Report
- 7. KGS Group, 2019a, Pennock Creek and Kaministiquia Floodplain Mapping Update Study, LiDAR Project Report.
- 8. KGS Group, 2019b, Pennock Creek Floodplain Mapping Update Study, Hydrologic Report.
- 9. KGS Group, 2019c, Pennock Creek Floodplain Mapping Update Study, Hydraulic Report.
- 10. KGS Group, 2018, McVicar Creek Floodplain Mapping Update Study, Hydrologic Report.
- 11. Hatch Mott MacDonald, HMM, 2015, McIntyre River Floodplain Mapping Study Final Hydrology Report





APPENDIX A

INFRASTRUCTURE LOCATED WITHIN THE FLOOD HAZARD LIMIT



Critical Flood Criteria: >0.3m, >1.7 m/s, depth × velocity > 0.4 m²/s

Flood Event	Flow at Confluence with Neebing River (m ³ /s)	Structure Type	Address	Structure	U	тм	Depth (m)	Velocity (m/s)	Depth × Velocity (m²/s)	Comments	Map Sheet	HEC-RAS Model Station	HEC-RAS Structure ID	Bank
	(, , , , , , , , , , , , , , , , , , , ,						
										Water through the lot, and overtop the road.				
Regional Storm	52.41	Ancillary	NA	12	320090	5361571	0.68	0.02	0.02	An ancillary building within the flood zone.	331	T1_02_0.2811		Both
		Road	NA	13	320107	5361479	0.49	0.02	0.01	Road/Driveway is overtopped	331	T1_02_0.2811		Both
		Driveway	NA	14	320102	5360834	0.65	0.11	0.07	Culvert/Driveway is overtopped	331	T1_02_0.3441	C-029-T1_02	Both
										Water through the lot, part of the ancillary				
		Ancillary	NA	15	320036	5361043	0.41	0.01	0.00	building is in the flood zone	331	T1_02_0.3741		Both
		Bridge/Culvert	NA	5	320276	5365119	0.73	0.35	0.26	Road/Driveway is overtopped	353	P_01_11.001	C-008-P_01	Right
		Bridge/Culvert	94 VIBERT RD	6	320165	5365116	0.66	0.55	0.37	Culvert/Driveway is overtopped	353	P_01_11.129	B-009-P_01	Both
		Bridge/Culvert	3139 ARTHUR ST	3	321394	5360855	0.72	1.37	0.99	Private Bridge/Culvert is overtopped	354	P_01_9.476	B-006-P_01	Both
										Water through the lot, low areas are flooded,				_
		Lots	66 HIGHWAY 130	4	321194	5360800	0.25	0.00	0.00	buildings are not in the flood zone	354	P_01_9.758		Both
										Facility/Ancillary building above the Thunder				
		Ancillary	25TH SIDEROAD	1	322885	5360928	0.46	0.60	0.28	Lake is within the flood zone	355	P_01_7.018		
		Bridge/Culvert	25TH SIDEROAD	2	322393	5360529	0.58	1.13	0.66	Pedestrain bridge is overtopped	355	P_01_7.605	B-005-P_01	Both
		Road	MUD LAKE RD	42	313993	5364220	0.22	0.49	0.11	Mud Lake Rd is overtopped	1856	P_06_5.063	C-020-P_06	Both
										Driveway appears to be submerged by flood				
		Driveway	15 BAXENDALE DR	45	314596	5360855	0.16	0.17	0.03	water	1856	P_06_6.595		Both
		, ,								Part of the driveway appears to be submerged				
		Driveway	16 BAXENDALE DR	47	314635	5363215	0.32	1.55	0.49	by flood water	1856	P_06_6.632		Both
		Road	BAXENDALE DR	51	314733	5360800	0.04	1.90	0.07	Baxendale Dr. is overtopped	1856	P_06_6.729		Left
										Water through the lot, buildings are not in the				
		Lots	3 BAXENDALE DR	52	314739	5361587	0.29	1.77	0.51	flood zone.	1856	P_06_6.732		Left
										Driveway appears to be submerged by flood				
		Driveway	3 BAXENDALE DR	53	314758	5360529	0.11	1.38	0.16	water	1856	P_06_6.751		Left
		, í								Water through the lot, buildings are not in the				
		Lots	1052 BAXENDALE DR	54	314767	5360742	0.16	1.53	0.25	flood zone.	1856	P_06_6.751		Left
		Ancillary	4572 OLIVER RD	57	314848	5363238	0.06	0.03	0.00	Several ancillary buildings are in the flood zone	1856	P_06_6.85		Both
		Ancillary	4572 OLIVER RD	59	314853	5363111	0.06	0.00	0.00	Several ancillary buildings are in the flood zone	1856	P_06_6.85		Both
		Ancillary	4530 OLIVER RD	64	315174	5365123	0.14	0.04	0.01	An ancillary building in the flood zone	1857	P_06_7.194		Both
		Driveway	48 CENTRE ST	17	319389	5363618	0.08	0.79	0.06	Culvert/Driveway is overtopped	1886	T1_02_3.718	C-035-T1_02	Left
		,								Water through the lot, part of the ancillary				
		Ancillary	332 DAWSON ST	18	319405	5364111	0.16	0.18	0.03	building is in the flood zone	1886	T1_02_3.721		Left
		Driveway	332 DAWSON ST	19	319396		0.15	0.17	0.02	Culvert/Driveway is overtopped		T1_02_3.742	C-036-T1_02	
										Water through the lot, the ancillary building is				1
		Ancillary	332 DAWSON ST	20	319413	5364087	0.24	0.46	0.11	in the flood zone	1886	T1_02_3.746		Both
		· · ·								An ancillary building , at rear of the property lot,				
		Ancillary	68 CENTRE ST	21	319390	5363898	0.16	0.06	0.01	is in the flood zone	1886	T1_02_3.821		Right
		,	653 POLELINE RD	40	314758			1.49	0.68	Pedestrain bridge overtopped			B-018-P_06	Both

Invite Image: Type Address Image:		Flow at Confluence													
Road 88 MUD LAKE RD 43 314019 6344699 0.29 0.34 0.10 Mud Lake Rd sovertopped 1968 P.06, 5691 C-021-P.06 Both Driveway 166 WING RD 35 315131 586146 0.22 0.88 0.19 by flood water 1907 P.06, 2897 C-016-P.06 Both Lots 166 WING RD 36 315157 536316 0.54 0.54 0.14 Wing RD 1907 P.06, 2886 Soth Soth Road WING RD 37 315075 536316 0.54 0.54 0.14 Wing RD is overtopped 1907 P.06, 3.06 C-017-P.06 Both Road 202 WING RD 38 315141 5363350 0.51 0.00 0.46 submerged 1907 P.06, 3.06 C-017-P.06 Both Lots 208 WING RD 38 315141 5363363 0.30 0.21 0.00 Pole 1907 P.06, 3.06 Water spills overint propert spills over in thet fowater spills over in thet sover		with Neebing River	Structure		Structure					Depth ×			HEC-RAS	HEC-RAS	
Image: Constraint of the second sec	Flood Event	(m³/s)			ID			• • • •	• • •			Map Sheet			
Image: Constraint of the			Road	88 MUD LAKE RD	43	314019	5364699	0.29	0.34			1906	P_06_5.691	C-021-P_06	Both
Lots 186 WING RD 36 315157 5385141 0.94 0.50 0.48 buildings are not in the flood care 1907 P. 06.2.86 Both Image: Construction of the state of the st															
Inst Iss WING RD 36 31517 35814 0.94 0.50 0.48 buildings are not in the flood zone 1907 P. 06.2.861 C-017-P_06 Both Common C			Driveway	186 WING RD	35	315131	5363184	0.22	0.88		5	1907	P_06_2.879	C-016-P_06	Both
Road WING RD 37 315073 5383215 0.25 0.54 0.14 Wing Rd is overtopped 1907 P .06 3.081 C.017-P .06 Both Road 202 WING RD 38 315141 5383215 0.25 0.54 0.46 submerged 1907 P .06 3.081 C.017-P .06 Both Lois 208 WING RD 39 315128 5381335 0.17 0.01 0.00 zoter split to the lot. Building is not in the flood 1907 P _063.085 Laft Mark Acids provide proped 1907 P _063.058 Laft Submerged 1907 P _063.058 Laft Water split over left river bank and overtoped 1908 T_5_01_1463 C-051.7_01 Laft Mark 20 2 316650 536318 0.22 0.08 0.00 the private driverway. 1908 T_5_01_1464 C-019-P06 Both Mark 20 2 317660 536318 0.22 0.38 0.30 163.0 171.01.00 C-047.4_0.1											U ,				
Road 202 WING RD 38 315141 536353 0.51 0.90 0.46 submerged 107 P_06_3.006 Left Lots 208 WING RD 39 315128 5361336 0.17 0.01 0.00 Zone 1907 P_06_3.006 Left Road POLELINE RD 31 316676 5363630 0.30 0.21 0.06 Poleine Rd overtopped 1907 P_06_3.058 Both Driveway 460 POLELINE RD 32 316650 5363618 0.02 0.08 0.00 the private driveway. 1908 T5_01_1.403 C-051-T5_01 Left Bridge/Culvert 460 POLELINE RD 32 3165650 5363618 0.02 0.08 0.00 the private driveway. 1908 T5_01_1.404 Left Bridge/Culvert NA RASER RD 27 317366 5363361 0.33 0.37 Pedestrain bridge is overtopped 1909 T4_01_1.401 Borde/47.01 Bord Bridge/Culvert NA 28 3174															
Road 202 WING RD 38 315141 5363335 0.51 0.90 0.46 submerged 1907 P. 06_3.005 Left Lois 208 WING RD 39 315128 5361336 0.17 0.01 0.00 Zone 1907 P. 06_3.058 Bath Road POLELINE RD 31 31667 556603 0.20 0.21 0.06 Poleine Rd overtopped 1908 To.61.1.463 Co51-T5_01 Left Driveway 460 POLELINE RD 32 316660 5563618 0.02 0.88 0.00 the private driveway. 1908 To.6.1.1.463 Co51-T5_01 Left Road POLELINE RD 32 316660 5363148 0.31 0.38 0.12 CulvertOriveway. 1908 To.6.1.1.463 Co51-T5_01 Left Bridge/Culvert 34 RAS2 5363364 0.24 0.81 0.34 0.08 0.61 Co11.40 Co51-T5_01 Left Driveway 495 POLELINE RD 30 <t< td=""><td></td><td></td><td>Road</td><td>WING RD</td><td>37</td><td>315073</td><td>5363215</td><td>0.25</td><td>0.54</td><td></td><td>,</td><td>1907</td><td>P_06_3.081</td><td>C-017-P_06</td><td>Both</td></t<>			Road	WING RD	37	315073	5363215	0.25	0.54		,	1907	P_06_3.081	C-017-P_06	Both
Lots 208 WING RD 39 315128 5361336 0.17 0.01 0.00 zone 1907 P_06_3.058 Bath Read POLELINE RD 31 316767 5363603 0.21 0.06 Poleline Rd overtopped 1907 P_06_3.058 Bath Driveway 460 POLELINE RD 31 316876 536361 0.22 0.06 Poleline Rd overtopped 1908 P_06_3.058 Bath BridgalCulvert 394 7317366 536361 0.24 0.34 0.08 Polien Rd is overtopped 1908 P_06_4.228 C-019-P.06 Both Bridge/Culvert NA 28 317425 536352 0.23 1.63 0.37 Pedestrain bridge is overtopped 1909 T4_01_1.408 B-046-T4_01 Both Driveway 459 POLELINE RD 30 316357 536414 0.38 0.12 CulvertDriveway is overtopped 1909 T4_01_1.408 B-046-T4_01 Both Driveway 459 POLELINE RD 30 316357 5															
Lots 208 WING RD 39 31512 536136 0.17 0.01 0.00 zone 1907 P. 06.3068 Both Road POLELINE RD 31 316676 5363603 0.30 0.21 0.06 Poleine Rd overtoped 1908 T5.01 1.463 C-051-T5.01 Left Driveway 460 POLELINE RD 32 316665 5363681 0.22 0.08 0.00 the private driveway. 1908 T5.01 1.464 Left Road POLELINE RD 41 314386 5363881 0.24 0.34 0.08 Poline Rd is overtopped 1908 T6.01 1.464 Left Bridge/Culvert NA RA 28 317425 536356 0.23 1.83 0.37 Pedestain bridge is overtopped 1909 T4.01.1.401 Both Both Bridge/Culvert NA 28 317425 536356 0.23 1.63 0.37 Colere to Both 1.01 1.01 Both Doth 1.01			Road	202 WING RD	38	315141	5363535	0.51	0.90		-	1907	P_06_3.005		Left
Road POLELINE RD 31 316676 5363603 0.30 0.21 0.06 Poleline Rd overtopped 1908 T5_0T_1.463 C-051-T5_01 Left Driveway 460 POLELINE RD 32 316650 5363681 0.02 0.08 0.00 the private driveway. 1908 T5_0T_1.464 Left Mass POLELINE RD 41 311336 536381 0.24 0.34 0.08 Poline Rd is overtopped 1908 T5_0T_1.464 Left Bridge/Culvert NA 24 0.34 0.38 0.12 CluvertDriveway is overtopped 1909 T4_01_1.00 C-045-T4_01 Both Driveway 459 POLELINE RD 30 316659 5363674 0.24 0.61 0.15 CulvertDriveway is overtopped 1909 T4_01_1.401 B-046-T4_01 Both Driveway 459 POLELINE RD 33 315377 536138 0.14 0.88 0.14 CulvertDriveway is overtopped 1911 T1_02_2.3495 C-034+T_00 Both Drive															
Driveway 460 POLELINE RD 32 316650 5363618 0.02 0.08 0.00 the private driveway. 1908 T_5_01_1.464 Left Road POLELINE RD 41 314386 5363681 0.24 0.34 0.08 Poline Rd is overtopped 1908 P_5_01_1.464 Left Bridge/Culvert 394 FRASER RD 27 317366 5363535 0.23 1.63 0.37 Pedestrain bridge is overtopped 1908 P_5_01_1.4164 Both Driveway 459 POLELINE RD 30 316559 5363535 0.23 1.63 0.37 Pedestrain bridge is overtopped 1909 T_5_01_1.41 C-050-T_5_01 Both Driveway 40 CENTRE ST 16 319415 5364134 0.14 0.98 0.14 Culvert/Driveway is overtopped 1901 T_5_01_1.416 C-04-T_2.01 Both Driveway 40 CENTRE ST 16 319415 5364134 0.15 0.32 0.05 Culvert/Driveway is overtopped 1901 T_1_02_3.496 C-03+T_1_02					39										
Image Driveway 460 POLELINE RD 32 31665 536318 0.02 0.08 Month of the private driveway. 1908 T5_01_1.464 Left Road POLELINE RD 41 314386 5363181 0.24 0.34 0.08 Poline Rd is overtopped 1908 P.d.e.1208 C-019-P.06 Both Bridge/Culvert NA 27 317366 5363184 0.31 0.38 0.12 Culvert/Driveway is overtopped 1909 T4_01_1.00 Bode-T4_01 Both Driveway 405 POLELINE RD 30 316537 0.24 0.61 0.15 Culvert/Driveway is overtopped 1909 T4_01_1.00 Bode-T4_01 Both Driveway 40 CENTRE ST 16 31915 536318 0.14 0.98 0.14 Culvert/Driveway is overtopped 1911 T_1023495 C-034-T1_02 Both Driveway 174 WING RD 34 315098 536328 0.21 0.11 water 1932 P.6E2751 C-014-P06 Both <tr< td=""><td></td><td></td><td>Road</td><td>POLELINE RD</td><td>31</td><td>316676</td><td>5363603</td><td>0.30</td><td>0.21</td><td></td><td>• •</td><td>1908</td><td>T5_01_1.463</td><td>C-051-T5_01</td><td>Left</td></tr<>			Road	POLELINE RD	31	316676	5363603	0.30	0.21		• •	1908	T5_01_1.463	C-051-T5_01	Left
Road POLELINE RD 41 314386 5363681 0.24 0.34 0.08 Poline Rd is overlopped 1908 P_06_4.228 C-019-P_06 Both Bridge/Culvert 394 FRASER RD 27 317366 5363184 0.31 0.38 0.12 Culvert/Driveway is overlopped 1909 T4_01_1.009 C-045-T4_01 Both Bridge/Culvert NA 28 317425 5363535 0.23 1.63 0.37 Pedestrain bridge is overlopped 1909 T4_01_1.001 B-046-T4_01 Both Driveway 459 POLELINE RD 30 316659 5363574 0.24 0.61 0.15 Culvert/Driveway is overlopped 1911 T1_02_3.495 C-034-T1_02 Both Bridge/Culvert 589 POLELINE RD 33 31507 5364184 0.14 0.98 0.14 Culvert/Driveway is overlopped 1911 T1_02_3.495 C-034-T1_02 Both Driveway 174 WING RD 34 315098 5363422 0.51 0.21 0.11 Water 1932															
Bridge/Culvert 394 FRASER RD 27 317366 5363184 0.31 0.38 0.12 Culvert/Driveway is overtopped 1909 T4_01_1.009 C-045-T4_01 Both Image: Culvert NA 28 317425 536335 0.23 1.63 0.37 Pedestrain bridge is overtopped 1909 T4_01_1.401 B-046-T4_01 Both Driveway 459 POLELINE RD 30 316659 5363574 0.24 0.61 0.15 Culvert/Driveway is overtopped 1909 T5_01_1.41 C-050-T5_01 Both Driveway 40 CENTRE ST 16 319415 5361318 0.14 0.98 0.14 Culvert/Driveway is overtopped 1911 T1_02_3.495 C-034-T1_02 Both Bridge/Culvert 589 POLELINE RD 33 315377 536419 0.15 0.32 0.05 Culvert/Driveway is overtopped 1932 P_06_2.751 C-015-P_06 Both Driveway 174 WING RD 34 315085 5363289 0.23 0.77 0.18 Private crossing is ov			Driveway		32										
Bridge/Culvert NA 28 317425 5363535 0.23 1.63 0.37 Pedestrain bridge is overtopped 1909 T4_01_1.401 B-046-T4_01 Both Driveway 40 CENTRE ST 16 319415 5363374 0.24 0.61 0.15 Culvert/Driveway is overtopped 1909 T4_01_1.401 B-046-T4_01 Both Driveway 40 CENTRE ST 16 319415 5363138 0.14 0.98 0.14 Culvert/Driveway is overtopped 1911 T1_02_3.495 C-034-T1_02 Both Driveway 174 WING RD 33 315377 5364194 0.15 0.32 0.05 Culvert is overtopped 1932 P_06_2.751 C-014-P_06 Both Driveway 174 WING RD 34 315098 536322 0.51 0.21 0.11 water 1932 P_06_2.751 C-016-P_06 Both Bridge/Culvert 3432 31547 536384 0.21 0.01 water 1932 T2_01_1.4.78 C-060-T2_01 Both <td></td> <td></td> <td>Road</td> <td>POLELINE RD</td> <td>41</td> <td>314386</td> <td></td> <td>0.24</td> <td>0.34</td> <td></td> <td></td> <td>1908</td> <td>P_06_4.228</td> <td>C-019-P_06</td> <td>Both</td>			Road	POLELINE RD	41	314386		0.24	0.34			1908	P_06_4.228	C-019-P_06	Both
Driveway 459 POLELINE RD 30 316659 5363574 0.24 0.61 0.15 Culvert/Driveway is overtopped 1909 T5_01_1.41 C-050-T5_01 Both Image: Construction of the start of			Bridge/Culvert	394 FRASER RD	27	317366	5363184	0.31	0.38	0.12	Culvert/Driveway is overtopped	1909	T4_01_1.009	C-045-T4_01	Both
Driveway 40 CENTRE ST 16 319415 5361318 0.14 0.98 0.14 Culvert/Driveway is overtopped 1911 T1_02_3.495 C-034-T1_02 Both Bridge/Culvert 589 POLELINE RD 33 315377 5364194 0.15 0.32 0.05 Culvert/Driveway is overtopped 1932 P_06_2.31 C-014-P_06 Both Driveway 174 WING RD 34 315098 5363422 0.51 0.21 0.11 water 1932 P_06_2.751 C-015-P_06 Both Bridge/Culvert 3432 11/17 HWY 24 318563 5362389 0.23 0.77 0.18 Private crossing is overtopped 1935 T2_01_1.478 C-060-T2_01 Both Road NA 26 316412 5360834 0.21 0.06 0.01 Culvert/Driveway is overtopped 1959 T3_02_1.372 C-044-T3_02 Both Bridge/Culvert NA 10 318951 536381 0.20 0.02 0.00 Culvert/Driveway is overtopped 1960			Bridge/Culvert	NA	28	317425	5363535	0.23	1.63	0.37	Pedestrain bridge is overtopped	1909	T4_01_1.401	B-046-T4_01	Both
Image: Culvert 589 POLELINE RD 33 315377 5364194 0.15 0.32 0.05 Culvert is overtopped 1932 P_06_2.31 C-014-P_06 Both Driveway 174 WING RD 34 315098 5363422 0.51 0.21 0.11 water 1932 P_06_2.31 C-014-P_06 Both Bridge/Culvert 3432 11/17 HWY 24 318563 5362389 0.23 0.77 0.18 Private crossing is overtopped 1932 P_06_2.71 C-015-P_06 Both Main Road NA 26 316412 5360834 0.21 0.06 0.01 Culvert/Driveway is overtopped 1935 T_2.01_1.478 C-015-P06 Both Main Road NA 26 316412 5360834 0.21 0.06 0.01 Culvert/Driveway is overtopped 1995 T_3.02_1.372 C-044-T302 Both Main Road VIBERT RD RAMP 7 319429 5361381 0.20 0.02 0.00 Culvert is overtopped			Driveway	459 POLELINE RD	30	316659	5363574	0.24	0.61	0.15	Culvert/Driveway is overtopped	1909	T5_01_1.41	C-050-T5_01	Both
Driveway 174 WING RD 34 315098 5363422 0.51 0.21 0.11 water 1932 P_06_2.751 C-015-P_06 Both Composition Bridge/Culvert 3432 11/17 HWY 24 31863 5362389 0.23 0.77 0.18 Private crossing is overtopped 1935 T2_01_1.478 C-000-T2_01 Both Road NA 26 316412 5360834 0.21 0.06 0.01 Culvert/Driveway is overtopped 1955 T3_01_2_1.372 C-044-T3_02 Both Bridge/Culvert NA 10 318951 5363681 0.20 0.02 0.00 Culvert/Driveway is overtopped 1950 T3_01_0_1.03 C-044-T3_02 Both Maad VIBERT RD RAMP 7 319429 5361318 0.89 0.48 0.43 Road overtopped 1961 P_02_1.289 Both Driveway NA 8 319091 5363574 0.08 0.01 Driveway is overtopped 1961 P_02_1.289 Both			Driveway	40 CENTRE ST	16	319415	5361318	0.14	0.98	0.14	Culvert/Driveway is overtopped	1911	T1_02_3.495	C-034-T1_02	Both
Image: Driveway 174 WING RD 34 315098 5363422 0.51 0.21 0.11 water 1932 P_06_2.751 C-015-P_06 Both Image: Driveway 3432 11/17 HWY 24 318563 5362389 0.23 0.77 0.18 Private crossing is overtopped 1935 T2_01_1.478 C-060-T2_01 Both Image: Driveway Road NA 26 316412 5360834 0.21 0.06 0.01 Culvert/Driveway is overtopped 1959 T3_02_1.372 C-044-T3_02 Both Image: Driveway NA 10 318951 536381 0.20 0.02 0.00 Culvert is overtopped 1960 T3_01_0.103 C-040-T3_01 Both Image: Driveway NA 10 318951 536381 0.20 0.02 0.00 Culvert is overtopped 1960 T3_01_0.103 C-040-T3_01 Both Image: Driveway NA 8 319091 536374 0.08 0.01 Driveway is overtopped 1961 P_02_1.0.98			Bridge/Culvert	589 POLELINE RD	33	315377	5364194	0.15	0.32	0.05	Culvert is overtopped	1932	P_06_2.31	C-014-P_06	Both
Bridge/Culvert 3432 11/17 HWY 24 318563 5362389 0.23 0.77 0.18 Private crossing is overtopped 1935 T2_01_1.478 C-060-T2_01 Both Road NA 26 316412 5360334 0.21 0.06 0.01 Culvert/Driveway is overtopped 1959 T3_02_1.372 C-044-T3_02 Both Bridge/Culvert NA 10 318951 5363681 0.20 0.02 0.00 Culvert/Driveway is overtopped 1960 T3_01_0.103 C-040-T3_01 Both Road VIBERT RD RAMP 7 319429 5361318 0.89 0.48 0.43 Road overtopped 1961 P_03_0.086 Left Driveway NA 8 319091 5361479 0.11 0.23 0.03 Road overtopped 1961 P_102_1.289 Both Road HIGHWAY 130 11 319620 5361479 0.11 0.23 0.03 Road overtopped 1961 T1_01_0.498 C-027-T1_0 Both <											Driveway appears to be submerged by flood				
Road NA 26 316412 5360834 0.21 0.06 0.01 Culvert/Driveway is overtopped 1959 T3_02_1.372 C-044-T3_02 Both Image: Culvert NA 10 318951 5363681 0.20 0.02 0.00 Culvert is overtopped 1960 T3_01_0.103 C-040-T3_01 Both Image: Culvert NA 8 319091 5363574 0.08 0.48 0.43 Road overtopped 1961 P_03_0.086 Left Image: Culvert NA 8 319091 5363574 0.08 0.08 0.01 Driveway is overtopped 1961 P_02_1.289 Both Image: Culvert NA 8 319091 5363574 0.08 0.03 Road overtopped 1961 T1_01_0.498 C-027-T1_01 Both Image: Culvert Road VIBERT RD N 22 31913 5364681 0.10 0.12 0.01 Vibiert Rd N is overtopped 1961 T2_01_0.498 C-027-T1_01 Both Both			Driveway	174 WING RD	34	315098	5363422	0.51	0.21	0.11	water	1932	P_06_2.751	C-015-P_06	Both
Bridge/Culvert NA 10 318951 5363681 0.20 0.02 0.00 Culvert is overtopped 1960 T3_01_0.103 C-040-T3_01 Both Road VIBERT RD RAMP 7 319429 5361318 0.89 0.48 0.43 Road overtopped 1961 P_03_0.086 Left Driveway NA 8 319091 5363574 0.08 0.01 Driveway is overtopped 1961 P_02_1.289 Both Road HIGHWAY 130 11 319620 5361479 0.11 0.23 0.03 Road overtopped 1961 T1_01_0.498 C-027-T1_01 Both Road VIBERT RD N 22 319113 5364681 0.10 0.12 0.01 Vibiert Rd N is overtopped 1961 T1_01_0.498 C-027-T1_01 Both Driveway 221 VIBERT RD 23 319096 5365132 0.03 0.14 0.00 Culvert/Driveway is overtopped 1961 T2_01_0.484 C-038-T2_01 Left Driveway <			Bridge/Culvert	3432 11/17 HWY	24	318563	5362389	0.23	0.77	0.18	Private crossing is overtopped	1935	T2_01_1.478	C-060-T2_01	Both
Road VIBERT RD RAMP 7 319429 5361318 0.89 0.48 0.43 Road overtopped 1961 P_03_0.086 Left Image: Construction of the cons			Road	NA	26	316412	5360834	0.21	0.06	0.01	Culvert/Driveway is overtopped	1959	T3_02_1.372	C-044-T3_02	Both
Driveway NA 8 319091 5363574 0.08 0.01 Driveway is overtopped 1961 P_02_1.289 Both Road HIGHWAY 130 11 319620 5361479 0.11 0.23 0.03 Road overtopped 1961 T1_01_0.498 C-027-T1_01 Both Road VIBERT RD N 22 319113 5364681 0.10 0.12 0.01 Vibiert Rd N is overtopped 1961 T2_01_0.1901 Both Driveway 221 VIBERT RD 23 319096 5365132 0.03 0.14 0.00 Culvert/Driveway is overtopped 1961 T2_01_0.484 C-038-T2_01 Left Driveway NA 25 317573 5361043 0.36 0.18 0.06 Culvert/Driveway is overtopped 1961 T3_02_0.088 C-057-T3_02 Both Driveway NA 25 317573 5363586 0.05 0.17 0.01 Poline Rd is overtopped 1961 T3_02_0.088 C-057-T3_02 Both Doth Drine Rd is ov			Bridge/Culvert	NA	10	318951	5363681	0.20	0.02	0.00	Culvert is overtopped	1960	T3_01_0.103	C-040-T3_01	Both
Road HIGHWAY 130 11 319620 5361479 0.11 0.23 0.03 Road overtopped 1961 T1_01_0.498 C-027-T1_01 Both Moad VIBERT RD N 22 31913 5364681 0.10 0.12 0.01 Vibiert Rd N is overtopped 1961 T2_01_0.1901 Both Driveway 221 VIBERT RD 23 31906 5365132 0.03 0.14 0.00 Culvert/Driveway is overtopped 1961 T2_01_0.484 C-038-T2_01 Left Driveway NA 25 317573 5361043 0.36 0.18 0.06 Culvert/Driveway is overtopped 1961 T3_02_0.088 C-057-T3_02 Both Road POLELINE RD 29 317415 5363586 0.05 0.17 0.01 Poline Rd is overtopped 1983 T4_01_1.467 C-047-T4_01 Both			Road	VIBERT RD RAMP	7	319429	5361318	0.89	0.48	0.43	Road overtopped	1961	P_03_0.086		Left
Road VIBERT RD N 22 319113 5364681 0.10 0.12 0.01 Vibiert Rd N is overtopped 1961 T2_01_0.1901 Both Driveway 221 VIBERT RD 23 319096 5365132 0.03 0.14 0.00 Culvert/Driveway is overtopped 1961 T2_01_0.484 C-038-T2_01 Left Driveway NA 25 317573 5361043 0.36 0.18 0.06 Culvert/Driveway is overtopped 1961 T3_02_0.088 C-057-T3_02 Both Road POLELINE RD 29 317415 5363586 0.05 0.17 0.01 Poline Rd is overtopped 1983 T4_01_1.467 C-047-T4_01 Both			Driveway	NA	8	319091	5363574	0.08	0.08	0.01	Driveway is overtopped	1961	P_02_1.289		Both
Road VIBERT RD N 22 319113 5364681 0.10 0.12 0.01 Vibiert Rd N is overtopped 1961 T2_01_0.1901 Both Driveway 221 VIBERT RD 23 31909 5365132 0.03 0.14 0.00 Culvert/Driveway is overtopped 1961 T2_01_0.484 C-038-T2_01 Left Driveway NA 25 317573 5361043 0.36 0.18 0.06 Culvert/Driveway is overtopped 1961 T3_02_0.088 C-057-T3_02 Both Road POLELINE RD 29 317415 5363586 0.05 0.17 0.01 Poline Rd is overtopped 1983 T4_01_1.467 C-047-T4_01 Both			Road	HIGHWAY 130	11	319620		0.11	0.23	0.03	Road overtopped	1961		C-027-T1_01	Both
Driveway 221 VIBERT RD 23 31909 5365132 0.03 0.14 0.00 Culvert/Driveway is overtopped 1961 T2_01_0.484 C-038-T2_01 Left Driveway NA 25 317573 5361043 0.36 0.18 0.06 Culvert/Driveway is overtopped 1961 T3_02_0.088 C-037-T3_02 Both Road POLELINE RD 29 317415 5363586 0.05 0.17 0.01 Poline Rd is overtopped 1983 T4_01_1.467 C-047-T4_01 Both			Road	VIBERT RD N	22	319113		0.10	0.12		Vibiert Rd N is overtopped	1961			Both
Driveway NA 25 317573 5361043 0.36 0.18 0.06 Culvert/Driveway is overtopped 1961 T3_02_0.088 C-057-T3_02 Both Model Road POLELINE RD 29 317415 5363586 0.05 0.17 0.01 Poline Rd is overtopped 1983 T4_01_1.467 C-047-T4_01 Both			Driveway	221 VIBERT RD	23	319096			0.14		Culvert/Driveway is overtopped	1961		C-038-T2 01	
Road POLELINE RD 29 317415 5363586 0.05 0.17 0.01 Poline Rd is overtopped 1983 T4_01_1.467 C-047-T4_01 Both									0.18		· · ·			_	
														—	
				VIBERT RD	9	319085	5363586	0.22	0.08		Vibiert Rd is overtopped	1986		C-011-P 02	Both

Critical Flood Criteria: >0.3m, >1.7 m/s, depth × velocity > 0.4 m²/s

with Neoling Elver (mY8) Structure Type Address Structure 10 UTM Depth (m) Depth (m)<				
100 YR 34.14 Anoliary NA 12 32009 5891479 0.44 0.01 ancliary building within the fload zone Priveway NA 14 320107 5891479 0.44 0.01 0.01 BraddDUveway is overtopped BridgeCulvent NA 14 320102 5806181 0.38 0.02 0.01 BraddDUveway is overtopped BridgeCulvent 34 VIEERT RD 6 320165 5865116 0.47 0.51 0.24 CulvetTDreway is overtopped BridgeCulvent 3139 ARTINE ST 312384 5360215 0.56 1.53 0.68 Pedestrinibridge is overtopped Driveway 49 CENTRE ST 17 314385 536215 0.10 1.28 0.12 CulvertDriveway is overtopped Ancillary 332 DAWSON ST 19 315085 536411 0.05 0.11 0.01 2.04ertDriveway is overtopped Ancillary 332 DAWSON ST 19 31505 536411 0.05 0.06 the flood zone Ancillary building is in the f		Map HEC-RAS Model Sheet Station	I HEC-RAS Structure ID	Bank
Road NA 13 320107 334170 0.01 0.01 Road/Driveway is overtopped Driveway NA 14 320102 5986180 0.61 0.08 0.051 CulvetTO/Inveway is overtopped Bridge/Culvert 94 VibERT RD 6 320165 5986116 0.47 0.51 0.24 CulvetTO/Inveway is overtopped Bridge/Culvert 321394 598052 0.56 1.53 0.98 Private Bridge/Culvert is overtopped Bridge/Culvert 25114 SIDEROAD 2 32233 5980521 0.51 0.88 Detection is overtopped Driveway 16 BAXENDALE DR 47 31435 593215 0.10 1.28 0.12 CulvertOr/Invewy is overtopped Ancillary 332 DAWSON ST 18 319405 593411 0.05 0.11 0.01 Euler Driveway is overtopped Ancillary 332 DAWSON ST 20 319413 5394087 0.17 0.35 0.06 the flood zone Driveway 332 DAWSON ST 20 31	oad. An			
Driveway NA 14 32012 550634 0.61 0.06 Culvert/Inversing soverlopped BridgeCulvert NA 5 32076 5366119 0.38 0.02 0.01 Road/Driversing is overlopped BridgeCulvert 319 Visiter 313 ATTUR ST 32134 530655 0.55 1.53 0.86 Private BridgeCulvert SingleCulvert Sin	33	331 T1_02_0.2811		Both
Image Culvert NA 5 320276 5986118 0.0.2 0.0.1 ReadDInvewsy is overtopped Image Culvert 3139 ARTHUR ST 3 321394 598055 0.56 1.53 0.86 Private Bridge/Culvert 13139 ARTHUR ST 3 321394 5980529 0.31 0.89 Pedestrain bridge is overtopped Image Culvert 2139 ARTHUR ST 3 321394 5980529 0.31 0.89 Pedestrain bridge is overtopped Image Culvert 18 BAXENDALE DR 47 714355 5983215 0.10 1.28 0.12 Culvert/Driverwy is overtopped Image Culvert 322 DAWSON ST 18 319405 5984111 0.05 0.11 0.01 Duilding is in the flood zone Image Culvert 322 DAWSON ST 19 31939 5386910 0.7 0.14 0.01 Culvert/Driverwy is overtopped Image Culvert 322 DAWSON ST 19 319396 5383690 0.7 0.14 0.01 Culvert/Driverwy is overtopped Image Culvert 68 CENTRE ST	33	331 T1_02_0.2811		Both
Bridge/Culvert 94 VIBERT RD 6 320165 5363116 0.47 0.51 0.24 Culvert/Dreway is overtopped Bridge/Culvert 33 23194 330965 0.66 1.53 0.96 Private Bridge/Culvert Bridge/Culvert 251H SIDEROAD 2 322333 3309629 0.31 0.89 0.28 Pertestrain bridge is overtopped Driveway 16 BAXENDALE DR 47 314935 538315 0.10 1.28 0.12 Culvert/Driveway is overtopped Ancilary 332 DAWSON ST 18 319405 536303 0.07 0.14 0.01 Duilvert/Driveway is overtopped Ancilary 332 DAWSON ST 19 319395 536303 0.07 0.14 0.01 Duilvert/Driveway is overtopped Ancilary 332 DAWSON ST 20 319413 5364087 0.17 0.35 0.06 An ancilary buildin the flood zone Ancilary 832 DAWSON ST 20 319413 5364029 0.34 1.52 0.52 Petestrain bridge overtopped Ancilary t	33	331 T1_02_0.3441	C-029-T1_02	Both
Bitdge/Culvert 3139 ARTHUR ST 3 312394 5308659 0.66 1.53 0.66 Private Bridge/Culvert is overtopped Bitdge/Culvert 25TH SIDEROAD 2 322393 380659 0.31 0.89 0.28 Peteratin bridge is overtopped Driveway 16 BAXENDALE DR 47 314635 538315 0.10 1.28 0.12 Dy Ifod water Driveway 48 CENTRE ST 17 319395 536318 0.12 0.04 Dy Ifod water Ancillary 332 DAWSON ST 18 319405 5364111 0.05 0.11 0.01 building is in the flood zone Ancillary 332 DAWSON ST 20 319413 5364067 0.17 0.35 0.06 the flood zone An ancillary building is an entillary building at rear of the prope Ancillary 66 CENTRE ST 21 319990 536489 0.44 0.37 0.05 Mul Lake R is overtopped Period Read 88 MUD LAKE RD 43 314019 5364499 0.14 <td>35</td> <td>353 P_01_11.001</td> <td>C-008-P_01</td> <td>Right</td>	35	353 P_01_11.001	C-008-P_01	Right
BridgerCulvert 25TH SIDEROAD 2 322393 5380829 0.31 0.89 0.28 Pedestain bridge is overtopped Driveway 16 BAXENDALE DR 47 314635 5383215 0.10 1.28 0.12 by flood water Driveway 46 CENTRE ST 17 319395 5380316 0.12 0.96 0.12 Culvert/Driveway is overtopped Ancillary 332 DAWSON ST 18 319405 536401 0.05 0.11 0.01 Culvert/Driveway is overtopped Ancillary 332 DAWSON ST 19 319396 536300 0.07 0.14 0.01 Culvert/Driveway is overtopped Ancillary 332 DAWSON ST 20 319413 536497 0.17 0.35 Molett Driveway is overtopped Ancillary 68 CENTRE ST 21 319305 536398 0.04 0.00 is in the flood zone Bridge/Culvert 63 POLELINE RD 40 314795 5364398 0.41 0.37 0.05 Mult Lake R1 is overtopped Road	35	353 P_01_11.129	B-009-P_01	Both
Image: Constraint of the second state of th	35	354 P_01_9.476	B-006-P_01	Both
Onveway 16 BAXENDALE DR 47 31438 533215 0.10 1.28 0.12 by flood water Improvement 48 CENTRE ST 17 31939 536318 0.12 0.96 0.12 CulvertDirveway is overtopped Ancillary 332 DAWSON ST 18 319405 536318 0.01 0.01 Duilding is in the flood zone Driveway 332 DAWSON ST 19 31938 536308 0.07 0.14 0.01 Duilding is in the flood zone Improvement 32 DAWSON ST 20 319413 3564087 0.17 0.35 0.66 the flood zone Improvement 65 CENTRE ST 21 31939 536388 0.04 0.00 is in the flood zone Improvement 65 SPOLELINE RD 40 31478 5363422 0.54 1.52 2.52 Pedestrain bridge overtopped Improvement 166 WING RD 35 315131 536348 0.18 0.99 0.14 0.97 Mad Lake RD 16.9 16.9 16.9	35	355 P_01_7.605	B-005-P_01	Both
Driveway 48 CENTRE ST 17 319389 5963618 0.12 0.96 0.12 CluvertDriveway is overtopped Ancillary 332 DAWSON ST 18 319405 5364111 0.05 0.11 0.01 CluvertDriveway is overtopped Driveway 332 DAWSON ST 19 319396 5363060 0.07 0.14 0.01 CluvertDriveway is overtopped Ancillary 332 DAWSON ST 20 319413 5364087 0.17 0.35 0.06 the flood zone Ancillary 332 DAWSON ST 20 319413 5364087 0.17 0.35 0.06 Ma ancillary building, at rear of the prope Ancillary 332 DAWSON ST 21 319305 5363486 0.08 0.04 0.00 is in the flood zone Bridge/Culvert 658 POLELINE RD 43 314019 5364689 0.14 0.37 0.05 Mul Lake Rd is overtopped Driveway 186 WING RD 36 315151 536314 0.86 0.38 0.31 0.31 0.31	nerged			
Anciliary 332 DAWSON ST 18 319405 5364111 0.05 0.11 Water through the lot, part of the ancillary Driveway 332 DAWSON ST 19 319396 5363603 0.07 0.14 0.01 Culvert/Driveway is overtopped Ancillary 332 DAWSON ST 20 319413 5364087 0.17 0.35 0.06 the flood zone Ancillary 68 CENTRE ST 21 319390 5363898 0.08 0.04 0.00 An ancillary building, at rear of the prope is in the flood zone Bridge/Culvert 68 CENTRE ST 21 319390 5363898 0.04 0.00 Mater through the lot, brain the ancillary building, at rear of the prope is in the flood zone Bridge/Culvert 68 CENTRE ST 21 319390 5363849 0.14 0.37 0.05 Multa RA RA RIS overtopped Close 186 WING RD 36 315131 5363140 0.18 0.99 0.18 Bridge/Culvert Na vater through the lot, low areas are flooc building are not in the flood zone Lots 186 WING RD 38 31	185	1856 P_06_6.632		Both
Anciliary 332 DAWSON ST 18 319405 5364111 0.05 0.11 0.01 Duilding is in the flood zone Anciliary 332 DAWSON ST 19 319305 536303 0.07 0.14 0.01 CulverDriveway is overdopped Anciliary 332 DAWSON ST 20 319415 5364087 0.17 0.35 0.06 the flood zone Mater through the lot, the anciliary building is in the lood zone Anciliary 68 CENTRE ST 21 319305 53638422 0.34 1.52 0.52 Pedestrain bridge overtopped Bridge/Culvert 653 POLELINE RD 40 314758 5364699 0.14 0.37 0.05 Mud Lake Rd is overtopped Part of the driveway appears to be subm Driveway 186 WING RD 36 315157 5365141 0.86 0.38 0.33 building is an ot in the flood zone A side road of a private property appears to be subm Lots 186 WING RD 36 315157 5365141 0.86 0.33 buildings are not in the flood zone A side road of a private propery appears to be submerg		1886 T1_02_3.718	C-035-T1_02	Left
Driveway 332 DAWSON ST 19 319396 5363603 0.07 0.14 0.01 Culver/Driveway is overtopped Ancillary 332 DAWSON ST 20 319413 5364087 0.17 0.35 0.06 the flood zone Ancillary 68 CENTRE ST 21 319309 5363898 0.08 0.04 0.00 is in the flood zone Bridge/Culvert 683 POLELINE RD 40 314758 5363422 0.34 1.52 0.52 Pedestrain bridge overtopped Driveway 186 WING RD 35 315131 5363184 0.18 0.99 0.18 pt of the driveway appears to be subme Driveway 186 WING RD 36 315157 5365141 0.86 0.38 0.33 buildings are not in the flood zone Road 202 WING RD 38 315141 5363525 0.41 0.75 0.31 Water through the lot, low areas are flood Lots 186 WING RD 38 315141 5363535 0.41 0.75 0.31 Building is not in the				
Anciliary 332 DAWSON ST 20 319413 5364087 0.17 0.35 0.06 the flood zone Anciliary 68 CENTRE ST 21 319390 5363988 0.08 0.04 0.00 is in the flood zone Bridge/Culvert 68 ST POLELINE RD 40 314758 5363422 0.34 1.52 0.52 Pedestrain bridge overtopped Road 88 MUD LAKE RD 43 314709 5364289 0.14 0.37 0.05 Mud Lake Rd is overtopped Driveway 186 WING RD 36 315157 5365141 0.86 0.38 0.33 buildings are not in the flood zone Lots 186 WING RD 36 315157 5365141 0.86 0.38 0.33 buildings are not in the flood zone Road 202 WING RD 38 315141 5363353 0.41 0.75 0.31 submerged Lots 208 WING RD 39 315128 5363134 0.06 0.57 0.03 Poline Rd is overtopped Bridge/Culvert		1886 T1_02_3.721		Left
Image: Second state Ancillary 332 DAWSON ST 20 319413 5364087 0.17 0.35 0.06 the flood zone Ancillary 68 CENTRE ST 21 319390 5363898 0.08 0.04 0.00 Is in the flood zone Bridge/Culvert 653 POLELINE RD 40 314758 5363422 0.34 1.52 0.52 Pedestrain bridge overtopped Road 88 MUD LAKE RD 43 314019 5346499 0.14 0.37 0.05 Mud Lake Rd is overtopped Driveway 186 WING RD 35 315131 5365141 0.86 0.38 0.33 buildings are not in the flood zone Lots 186 WING RD 36 315175 5365141 0.86 0.38 0.33 buildings are not in the flood zone Road 202 WING RD 38 315141 536355 0.41 0.75 0.31 suberropedt appears Lots 208 WING RD 39 315128 536136 0.02 0.01 0.00 zone		1886 T1_02_3.742	C-036-T1_02	Both
Ancillary 68 CENTRE ST 21 31930 5363888 0.08 0.04 O.00 Ancillary building, at rear of the proper is in the flood zone Bridge/Culvert 653 POLELINE RD 40 314758 5363422 0.34 1.52 0.52 Pedestrain bridge overtopped Road 88 MUD LAKE RD 43 314019 53648499 0.14 0.37 0.05 Mud Lake Rd is overtopped Driveway 186 WING RD 35 315131 5363184 0.18 0.99 0.18 by flood water Lots 186 WING RD 36 315157 5365141 0.86 0.38 0.33 buildings are not in the flood zone Road 202 WING RD 38 315115 5365345 0.41 0.75 0.31 submerged Lots 208 WING RD 39 315128 5363136 0.02 0.01 0.00 zone Road POLELINE RD 41 314386 5563681 0.13 0.25 0.03 Culvert/Driveway is overtopped Bridg	-			
Ancillary 68 CENTRE ST 21 319390 5363898 0.08 0.04 0.00 is in the flood zone Bridge/Culvert 653 POLELINE RD 40 314785 5363422 0.34 1.52 0.52 Pedestrain bridge overlopped Road 88 MUD LAKE RD 43 314019 5364699 0.14 0.37 0.05 Mud Lake Rd is overlopped Driveway 186 WING RD 35 315131 5365141 0.86 0.99 0.18 by flood water Lots 186 WING RD 36 315157 5365141 0.86 0.38 0.33 buildings are not in the flood zone Road 202 WING RD 38 315141 5363535 0.41 0.75 0.31 submerged Lots 208 WING RD 39 315128 5361340 0.02 0.01 0.00 zone Road 202 WING RD 39 315128 5363136 0.02 0.01 0.00 zone Road 203 WING RD 39 31		1886 T1_02_3.746		Both
Bridge/Culvert 653 POLELINE RD 40 314758 5363422 0.34 1.52 0.52 Pedestrain bridge overtopped Road 88 MUD LAKE RD 43 314019 5364699 0.14 0.37 0.05 Mud Lake RI is overtopped Driveway 186 WING RD 35 315131 5363184 0.18 0.99 0.18 by flood water Lots 186 WING RD 36 315157 5365141 0.86 0.38 0.33 buildings are not in the flood zone Road 202 WING RD 38 315115 536535 0.41 0.75 0.31 submerged Water spill to the lot. Building is not in the flood zone A side road of a private property appears Vater spill to the lot. Building is not in the zone Vater spill to the lot. Building is not in the zone Road POLELINE RD 41 314366 5363184 0.06 0.57 0.03 Poline Rd is overtopped Bridge/Culvert 349 FRASER RD 27 317366 536314 0.46 0.47 0.03 Culvert/Driveway is overtopped <td></td> <td></td> <td></td> <td></td>				
Road 88 MUD LAKE RD 43 314019 5364699 0.14 0.37 0.05 Mud Lake Rd is overtopped Driveway 186 WING RD 35 315131 5363184 0.18 by flood water Lots 186 WING RD 36 315131 5365141 0.86 0.38 0.33 buildings are not in the flood zone Road 202 WING RD 38 315115 5365141 0.86 0.38 0.33 buildings are not in the flood zone Road 202 WING RD 38 315128 5365136 0.02 0.01 0.00 zone Lots 208 WING RD 39 315128 536336 0.13 0.25 0.03 Poline Rd is overtopped Midge/Culvert NA 28 317425 5363535 0.17 1.51 0.26 Pedestrain bridge is overtopped Driveway 49 POLELINE RD 28 317425 5363535 0.17 1.51 0.26 Pedestrain bridge is overtopped Driveway 49 POLELINE RD 30		1886 T1_02_3.821		Right
Driveway 186 WING RD 35 315131 5363184 0.18 0.99 0.18 by flood water Lots 186 WING RD 36 315157 5365141 0.86 0.38 0.33 buildings are not in the flood zone Road 202 WING RD 38 315117 5365141 0.86 0.38 0.33 buildings are not in the flood zone Road 202 WING RD 38 315111 536358 0.41 0.75 0.31 submerged parest property appears Lots 208 WING RD 39 315128 5361366 0.02 0.01 0.00 zone Road POLELINE RD 41 314386 5363681 0.13 0.25 0.03 Culvert/Driveway is overtopped Bridge/Culvert NA 28 317425 5363535 0.17 1.51 0.26 Pedestrain bridge is overtopped Driveway 40 CENTRE ST 16 319415 5361318 0.04 0.30 0.01 Culvert/Driveway is overtopped Driveway		1906 P_06_3.534	B-018-P_06	Both
Driveway 186 WING RD 35 315131 5363184 0.18 0.99 0.18 by flood water Lots 186 WING RD 36 315157 5365141 0.86 0.33 0.31 buildings are not in flood zone Road 202 WING RD 38 315127 5365141 0.86 0.33 submerged A side road of a private property appears submerged Lots 202 WING RD 39 315128 5361336 0.02 0.01 0.00 zone Road POLELINE RD 41 314386 5363681 0.13 0.25 0.03 Cluvert/Driveway is overtopped Bridge/Culvert NA 28 317425 536335 0.17 1.51 0.26 Pedestrain bridge is overtopped Driveway 459 POLELINE RD 30 31659 5363574 0.16 0.44 0.07 Cluvert/Driveway is overtopped Driveway 40 CENTRE ST 16 319415 536335 0.17 1.51 0.26 Pedestrain bridge is overtopped Driveway is over		1906 P_06_5.691	C-021-P_06	Both
Lots 186 WING RD 36 315157 5365141 0.86 0.33 Water through the lot, low areas are flood Road 202 WING RD 38 3151157 5365141 0.86 0.33 0.33 buildings are not in the flood zone Lots 202 WING RD 38 315114 536355 0.41 0.75 0.31 submerged Lots 208 WING RD 39 315128 5361364 0.02 0.01 0.00 zone Road POLELINE RD 41 314386 5363681 0.13 0.25 0.03 Poline Rd is overtopped Bridge/Culvert NA 28 317425 5363535 0.17 1.51 0.26 Pedestrain bridge is overtopped Driveway 459 POLELINE RD 30 316569 5363574 0.16 0.44 0.07 Culvert/Driveway is overtopped Driveway 40 CENTRE ST 16 319415 5361318 0.04 0.30 0.01 Culvert/Driveway is overtopped Driveway 174 WING RD	0			
Lots 186 WING RD 36 315157 5365141 0.86 0.38 0.33 buildings are not in the flood zone Road 202 WING RD 38 315141 536535 0.41 0.75 0.31 suberrged Lots 208 WING RD 39 315145 536335 0.041 0.75 0.31 suberrged Lots 208 WING RD 39 315145 536336 0.02 0.01 0.00 zone Mater spill to the lot. Building is not in the flood zone Side road of a private property appears suberrged Mater spill to the lot. Building is not in the flood zone Zone Water spill to the lot. Building is not in the flood zone Mater Spill to the lot. Building is not in the flood zone Road POLELINE RD 41 31436 536355 0.17 1.51 0.02 Pedestrain bridge is overtopped Mater Spill to the lot. Building is not in the flood zone Bridge/Culvert NA 28 317425 536355 0.17 1.51 0.26 Pedestrain bridge is overtopped Mater Spill to the lot. Building is not in the floo		1907 P_06_2.879	C-016-P_06	Both
Road 202 WING RD 38 315141 5363535 0.41 0.75 0.31 submerged Lots 208 WING RD 39 315128 5361336 0.02 0.01 0.00 zone Water spill to the lot. Building is not in the Lots 208 WING RD 39 315128 5361336 0.02 0.01 0.00 zone Water spill to the lot. Building is not in the Driveway 394 FRASER RD 27 317366 5363184 0.06 0.57 0.03 Poline Rd is overtopped Bridge/Culvert NA 28 317425 5363535 0.17 1.51 0.26 Pedestrain bridge is overtopped Driveway 459 POLELINE RD 30 316659 5363574 0.16 0.44 0.07 Culvert/Driveway is overtopped Driveway 40 CENTRE ST 16 319415 5361318 0.04 0.30 0.01 Culvert/Driveway is overtopped Driveway 174 WING RD 34 315087 5363542 0.35 0.14 0.05 water <t< td=""><td></td><td>1007 5 00 0000</td><td></td><td></td></t<>		1007 5 00 0000		
Road 202 WING RD 38 315141 5363535 0.41 0.75 0.31 submerged Construction Lots 208 WING RD 39 315128 5361336 0.02 0.01 0.00 zone Vater spill to the lot. Building is not in the lot. Lots 208 WING RD 39 315128 5361336 0.02 0.01 0.00 zone Image: Construction of the lot of the lot. Bridge/Culvert 394 FRASER RD 27 317366 5363184 0.06 0.57 0.03 Culvert/Driveway is overtopped Image: Construction of the lot constructing lot construction of the lot constructing lot construc		1907 P_06_2.886		Both
Lots 208 WING RD 39 315128 5361336 0.02 0.01 0.00 zone Made POLELINE RD 41 314386 5366381 0.13 0.25 0.03 Poline Rd is overtopped Bridge/Culvert 394 FRASER RD 27 317366 5363184 0.06 0.57 0.03 Culvert/Driveway is overtopped Bridge/Culvert NA 28 317425 5363555 0.17 1.51 0.26 Pedestrain bridge is overtopped Driveway 459 POLELINE RD 30 316659 5363574 0.16 0.44 0.07 Culvert/Driveway is overtopped Driveway 40 CENTRE ST 16 319415 5361318 0.04 0.30 0.01 Culvert/Driveway is overtopped Driveway 40 CENTRE ST 16 319415 5361318 0.04 0.30 0.01 Culvert/Driveway is overtopped Driveway 174 WING RD 34 315098 5363422 0.35 0.14 0.05 water Driveway		1007 0 00 0 005		1.4
Lots 208 WING RD 39 31512 5361336 0.02 0.01 0.00 zone Image: Construction of the strength of the strengt of the strength of the strength of the strengt of		1907 P_06_3.005		Left
Road POLELINE RD 41 314386 5363681 0.13 0.25 0.03 Poline Rd is overtopped Bridge/Culvert 394 FRASER RD 27 317366 5363184 0.06 0.57 0.03 Culvert/Driveway is overtopped Bridge/Culvert NA 28 317425 5363535 0.17 1.51 0.26 Pedestrain bridge is overtopped Driveway 459 POLELINE RD 30 316659 5363535 0.16 0.44 0.07 Culvert/Driveway is overtopped Driveway 40 CENTRE ST 16 319415 5361318 0.04 0.30 0.01 Culvert/Driveway is overtopped Driveway 40 CENTRE ST 16 319415 5361318 0.04 0.30 0.01 Culvert/Driveway appears to be submerged by flow Bridge/Culvert 589 POLELINE RD 34 315098 536322 0.35 0.14 0.05 water Driveway 174 WING RD 34 315098 5363289 0.18 0.65 0.12 Private crossing is overtopped<		4007 0 00 0 050		Dette
Bridge/Culvert 394 FRASER RD 27 317366 5363184 0.06 0.57 0.03 Culvert/Driveway is overtopped Bridge/Culvert NA 28 317425 5363535 0.17 1.51 0.26 Pedestrain bridge is overtopped Driveway 459 POLELINE RD 30 316659 5363574 0.16 0.44 0.07 Culvert/Driveway is overtopped Driveway 40 CENTRE ST 16 319415 5361318 0.04 0.30 0.01 Culvert/Driveway is overtopped Bridge/Culvert 589 POLELINE RD 33 315377 5364194 0.11 0.23 0.03 Culvert/Driveway is overtopped Driveway 174 WING RD 34 315098 5363422 0.35 0.14 0.05 water Driveway 174 WING RD 34 315098 5362389 0.18 0.65 0.12 Private crossing is overtopped Road NA 26 316412 5360834 0.17 0.04 0.01 Culvert/Driveway is overtopped <		1907 P_06_3.058 1908 P 06 4.228	C-019-P 06	Both Both
Bridge/Culvert NA 28 317425 5363535 0.17 1.51 0.26 Pedestrain bridge is overtopped Driveway 459 POLELINE RD 30 316659 5363574 0.16 0.44 0.07 Culvert/Driveway is overtopped Driveway 40 CENTRE ST 16 319415 5361318 0.04 0.30 0.01 Culvert/Driveway is overtopped Bridge/Culvert 589 POLELINE RD 33 315377 5364194 0.11 0.23 0.03 Culvert/Driveway is overtopped Driveway 174 WING RD 34 315098 5363422 0.35 0.14 0.05 water Driveway 174 WING RD 34 315098 5362389 0.18 0.65 0.12 Private crossing is overtopped Bridge/Culvert 3432 11/17 HWY 24 318563 5362389 0.18 0.65 0.12 Private crossing is overtopped Private crossing is overtopped 10 318951 5366381 0.17 0.04 0.01 Culvert/Driveway is overtopped <td></td> <td>1908 P_06_4.228 1909 T4 01 1.009</td> <td>C-019-P_06 C-045-T4 01</td> <td>Both</td>		1908 P_06_4.228 1909 T4 01 1.009	C-019-P_06 C-045-T4 01	Both
Driveway 459 POLELINE RD 30 316659 5363574 0.16 0.44 0.07 Culvert/Driveway is overtopped Driveway 40 CENTRE ST 16 319415 5361318 0.04 0.30 0.01 Culvert/Driveway is overtopped Bridge/Culvert 589 POLELINE RD 33 315377 5364194 0.11 0.23 0.03 Culvert/Driveway is overtopped Driveway 174 WING RD 34 315087 5363422 0.35 0.14 0.05 water Driveway 174 WING RD 34 315085 5363422 0.35 0.14 0.05 water Bridge/Culvert 3432 11/17 HWY 24 318563 5362389 0.18 0.65 0.12 Private crossing is overtopped Road NA 26 316412 5360834 0.17 0.04 0.01 Culvert/Driveway is overtopped Road NA 10 318951 5363681 0.12 0.02 0.00 Culvert is overtopped Road VIBERT		1909 T4_01_1.009	B-046-T4_01	Both
Driveway 40 CENTRE ST 16 319415 5361318 0.04 0.30 0.01 Culvert/Driveway is overtopped Bridge/Culvert 589 POLELINE RD 33 315377 5364194 0.11 0.23 0.03 Culvert is overtopped Driveway 174 WING RD 34 315098 5363422 0.35 0.14 0.05 water Bridge/Culvert 3432 11/17 HWY 24 318563 5362389 0.18 0.65 0.12 Private crossing is overtopped Road NA 26 316412 5360834 0.17 0.04 0.01 Culvert/Driveway is overtopped Bridge/Culvert NA 10 318951 5363681 0.12 0.02 0.00 Culvert/Driveway is overtopped Road VIBERT RD RAMP 7 319429 5361318 0.24 0.38 0.09 Road overtopped Driveway NA 8 319091 5363574 0.01 0.06 0.00 Driveway is overtopped Driveway NA <td></td> <td>1909 T5 01 1.41</td> <td>C-050-T5 01</td> <td>Both</td>		1909 T5 01 1.41	C-050-T5 01	Both
Bridge/Culvert 589 POLELINE RD 33 315377 5364194 0.11 0.23 0.03 Culvert is overtopped Driveway 174 WING RD 34 315096 5363422 0.35 0.14 0.05 water Bridge/Culvert 3432 11/17 HWY 24 318563 5363422 0.35 0.14 0.05 water Road NA 26 316412 5360834 0.17 0.04 0.01 Culvert/Driveway is overtopped Bridge/Culvert NA 26 316412 5363881 0.12 0.02 0.00 Culvert/Driveway is overtopped Road NA 10 318951 5363881 0.12 0.02 0.00 Culvert is overtopped Road VIBERT RD RAMP 7 319429 5361318 0.24 0.38 0.09 Road overtopped Driveway NA 8 319091 5365574 0.01 0.06 0.00 Driveway is overtopped Road HIGHWAY 130 11 319620 <td></td> <td>1909 15_01_1.41 1911 T1 02 3.495</td> <td>C-030-T5_0T</td> <td>Both</td>		1909 15_01_1.41 1911 T1 02 3.495	C-030-T5_0T	Both
Driveway 174 WING RD 34 315098 5363422 0.35 0.14 0.05 Driveway appears to be submerged by flow water Image: Stridge/Culvert 3432 11/17 HWY 24 318563 5362389 0.18 0.65 0.12 Private crossing is overtopped Image: Stridge/Culvert NA 26 316412 5360834 0.17 0.04 0.01 Culvert/Driveway is overtopped Image: Stridge/Culvert NA 26 316412 5360834 0.17 0.04 0.01 Culvert/Driveway is overtopped Image: Stridge/Culvert NA 10 318951 5363681 0.12 0.00 Culvert/Driveway is overtopped Image: Stridge/Culvert NA 10 318951 5363681 0.12 0.00 Culvert/Is overtopped Image: Stridge/Culvert NA 10 318951 5361318 0.24 0.38 0.09 Road overtopped Image: Stridge/Culvert NA 8 319091 5365374 0.01 0.06 0.00 Driveway is overtopped		1932 P 06 2.31	C-014-P 06	Both
Driveway 174 WING RD 34 315098 5363422 0.35 0.14 0.05 water Image: College		1932 F_00_2.31	C-014-P_00	BOILI
Bridge/Culvert 3432 11/17 HWY 24 318563 5362389 0.18 0.65 0.12 Private crossing is overtopped Road NA 26 316412 5360834 0.17 0.04 0.01 Culvert/Driveway is overtopped Bridge/Culvert NA 10 318951 5363681 0.12 0.02 0.00 Culvert/Driveway is overtopped Road VIBERT RD RAMP 7 319429 5361318 0.24 0.38 0.09 Road overtopped Driveway NA 8 319091 5363574 0.01 0.06 0.00 Driveway is overtopped Road HIGHWAY 130 11 319620 5361479 0.07 0.17 0.01 Road overtopped		1932 P 06 2.751	C-015-P 06	Both
Road NA 26 316412 5360834 0.17 0.04 0.01 Culvert/Driveway is overtopped Bridge/Culvert NA 10 318951 5363681 0.12 0.02 0.00 Culvert is overtopped Road VIBERT RD RAMP 7 319429 5361318 0.24 0.38 0.09 Road overtopped Driveway NA 8 319091 5363574 0.01 0.06 0.00 Driveway is overtopped Road HIGHWAY 130 11 319620 5361479 0.07 0.17 0.01 Road overtopped		1935 T2 01 1.478	C-060-T2 01	Both
Bridge/Culvert NA 10 318951 5363681 0.12 0.02 0.00 Culvert is overtopped Road VIBERT RD RAMP 7 319429 5361318 0.24 0.38 0.09 Road overtopped Driveway NA 8 319091 5363574 0.01 0.06 0.00 Driveway is overtopped Road HIGHWAY 130 11 319620 5361479 0.07 0.17 0.01 Road overtopped		1959 T3 02 1.372	C-044-T3 02	Both
Road VIBERT RD RAMP 7 319429 5361318 0.24 0.38 0.09 Road overtopped Driveway NA 8 319091 5363574 0.01 0.06 0.00 Driveway is overtopped Road HIGHWAY 130 11 319620 5361479 0.07 0.17 0.01 Road overtopped		1960 T3 01 0.103	C-044-13_02 C-040-T3 01	Both
Driveway NA 8 319091 5363574 0.01 0.06 0.00 Driveway is overtopped Road HIGHWAY 130 11 319620 5361479 0.07 0.17 0.01 Road overtopped		1961 P 03 0.086	0-040-13_01	Left
Road HIGHWAY 130 11 319620 5361479 0.07 0.17 0.01 Road overtopped		1961 P_03_0.086		Both
		1961 P_02_1.289 1961 T1 01 0.498	C-027-T1 01	Both
		1961 T2 01 0.1901	0-027-11_01	Both
Driveway 221 VIBERT RD 23 319113 5364681 0.04 0.06 0.00 Vibert R0 N is overlopped		1961 T2_01_0.1901	C-038-T2 01	Left
Driveway NA 25 319096 5365132 0.02 0.10 0.00 Culver/Driveway is overtopped		1961 T2_01_0.484	C-038-12_01 C-057-T3 02	Both
Driveway NA 25 3175/3 5361043 0.15 0.11 0.02 Curver/Univeway is overtopped Road VIBERT RD 9 319085 5363586 0.15 0.06 0.01 Vibiert Rd is overtopped		1961 13_02_0.088 1986 P 02 1.289	C-057-13_02 C-011-P 02	Both

Critical Flood Criteria: >0.3m, >1.7 m/s, depth × velocity > 0.4 m²/s

Return Period	Flow at Confluence with Neebing River (m ³ /s)	Structure Type	Address	Structure ID	UT	ГМ	Depth (m)	Velocity (m/s)	Depth × Velocity (m²/s)	Comments	Map Sheet	HEC-RAS Model Station	HEC-RAS Structure ID	Bank
										Water through the lot, and overtop the road. An				
50 Year	29.53	Ancillary	NA	12	320090	5361571	0.61	0.01	0.01	ancillary building within the flood zone.	331	T1_02_0.2811		Both
		Road	NA	13	320107	5361479	0.41	0.01	0.00	Road/Driveway is overtopped	331	T1_02_0.2811		Both
		Driveway	NA	14	320102	5360834	0.58	0.08	0.05	Culvert/Driveway is overtopped	331	T1_02_0.3441	C-029-T1_02	Both
		Bridge/Culvert	NA	5	320276	5365119	0.26	0.02	0.00	Road/Driveway is overtopped	353	P_01_11.001	C-008-P_01	Right
		Bridge/Culvert	94 VIBERT RD	6	320165	5365116	0.41	0.49	0.20	Culvert/Driveway is overtopped	353	P_01_11.129	B-009-P_01	Both
		Bridge/Culvert	3139 ARTHUR ST	3	321394	5360855	0.11	1.18	0.13	Private Bridge/Culvert is overtopped	354	P_01_9.476	B-006-P_01	Both
		Bridge/Culvert	25TH SIDEROAD	2	322393	5360529	0.19	0.81	0.15	Pedestrain bridge is overtopped	355	P_01_7.605	B-005-P_01	Both
		Driveway	48 CENTRE ST	17	319389	5363618	0.10	0.86	0.09	Culvert/Driveway is overtopped	1886	T1_02_3.718	C-035-T1_02	Left
										Water through the lot, part of the ancillary building				
		Ancillary	332 DAWSON ST	18	319405	5364111	0.02	0.10	0.00	is in the flood zone	1886	T1_02_3.721		Left
		Driveway	332 DAWSON ST	19	319396	5363603	0.16	0.15	0.02	Culvert/Driveway is overtopped	1886	T1_02_3.742	C-036-T1_02	Both
										Water through the lot, the ancillary building is in				
		Ancillary	332 DAWSON ST	20	319413	5364087	0.16	0.30	0.05	the flood zone	1886	T1_02_3.746		Both
										An ancillary building, at rear of the property lot, is				
		Ancillary	68 CENTRE ST	21	319390	5363898	0.07	0.03	0.00	in the flood zone	1886	T1_02_3.821		Right
		Bridge/Culvert	653 POLELINE RD	40	314758	5363422	0.29	1.47	0.42	Pedestrain bridge overtopped	1906	P 06 3.534	B-018-P 06	Both
		Road	88 MUD LAKE RD	43	314019	5364699	0.04	0.38	0.02	Mud Lake Rd is overtopped	1906	P 06 5.691	C-021-P 06	Both
										Part of the driveway appears to be submerged by				
		Driveway	186 WING RD	35	315131	5363184	0.11	0.93	0.10	flood water	1907	P 06 2.879	C-016-P 06	Both
										Water through the lot, low areas are flooded,				
		Lots	186 WING RD	36	315157	5365141	0.79	0.35	0.27	buildings are not in the flood zone	1907	P 06 2.886		Both
										A side road of a private property appears to be				
		Road	202 WING RD	38	315141	5363535	0.34	0.78	0.26	submerged	1907	P 06 3.005		Left
		Road	POLELINE RD	41	314386	5363681	0.05	0.22	0.01	Poline Rd is overtopped	1908	P 06 4.228	C-019-P 06	Both
		Bridge/Culvert	394 FRASER RD	27	317366	5363184	0.15	0.43	0.06	Culvert/Driveway is overtopped	1909	T4 01 1.009	C-045-T4 01	Both
-		Bridge/Culvert	NA	28	317425	5363535	0.15	1.44	0.22	Pedestrain bridge is overtopped	1909	T4 01 1.401	B-046-T4 01	Both
		Driveway	459 POLELINE RD	30	316659	5363574	0.14	0.39	0.05	Culvert/Driveway is overtopped	1909	T5 01 1.41	C-050-T5 01	Both
		Bridge/Culvert	589 POLELINE RD	33	315377	5364194	0.10	0.20	0.02	Culvert is overtopped	1932	P 06 2.31	C-014-P 06	Both
	-	Bhage/Barrent	OOOT OLLEINE IND	00	010011	0004104	0.10	0.20	0.02		1002	1_00_2.01	0 0141 _00	Dour
		Driveway	174 WING RD	34	315098	5363422	0.37	0.12	0.04	Driveway appears to be submerged by flood water	1932	P 06 2.751	C-015-P 06	Both
		Bridge/Culvert	3432 11/17 HWY	24	318563	5362389	0.17	0.58	0.10	Private crossing is overtopped	1935	T2 01 1.478	C-060-T2 01	Both
	+	Road	NA	24	316412	5360834	0.17	0.03	0.00	Culvert/Driveway is overtopped	1959	T3 02 1.372	C-044-T3 02	Both
	+	Bridge/Culvert	NA	10	318951	5363681	0.15	0.03	0.00	Culvert is overtopped	1959	T3_02_1.372 T3_01_0.103	C-040-T3 01	Both
	+	Road	VIBERT RD RAMP	7	318951	5361318	0.10	0.02	0.00		1960	P 03 0.086	0-040-13_01	Both
							0.23			Road overtopped			C 007 T4 04	
	+	Road	HIGHWAY 130	11	319620	5361479		0.16	0.01	Road overtopped	1961	T1_01_0.498	C-027-T1_01	Both
	+	Driveway	221 VIBERT RD	23	319096	5365132	0.14	0.15	0.02	Culvert/Driveway is overtopped	1961	T2_01_0.484	C-038-T2_01	Left
		Driveway	NA	25	317573	5361043	0.08	0.13	0.01	Culvert/Driveway is overtopped	1961	T3_02_0.088	C-057-T3_02	Both
		Road	VIBERT RD	9	319085	5363586	0.13	0.05	0.01	Vibiert Rd is overtopped	1986	P_02_1.289	C-011-P_02	Both

Critical Flood Criteria: >0.3m, >1.7 m/s, depth × velocity > 0.4 m²/s

Return Period	Flow at Confluence with Neebing River (m³/s)	Structure Type	Address	Structure ID	UT		Depth (m)	Velocity (m/s)	Depth × Velocity (m²/s)	Comments	Map Sheet	HEC-RAS Model Station	HEC-RAS Structure ID	Bank
25 Year	24.9	Driveway	NA	14	320102	5360833.5	0.47	0.00	0.00	Culvert/Driveway is overtopped	331	T1_02_0.3441	C-029-T1_02	Both
		Bridge/Culvert	94 VIBERT RD	6	320165	5365115.9	0.33	0.49	0.16	Culvert/Driveway is overtopped	353	P_01_11.129	B-009-P_01	Both
		Bridge/Culvert	NA	5	320276	5365119	0.14	0.02	0.00	Road/Driveway is overtopped	353	P_01_11.001	C-008-P_01	Right
		Bridge/Culvert	3139 ARTHUR ST	3	321394	5360854.5	0.10	1.01	0.10	Private Bridge/Culvert is overtopped	354	P_01_9.476	B-006-P_01	Both
		Bridge/Culvert	25TH SIDEROAD	2	322393	5360529.1	0.05	0.73	0.04	Pedestrain bridge is overtopped	355	P_01_7.605	B-005-P_01	Both
		Ancillary	68 CENTRE ST	21	319390	5363897.9	0.03	0.02	0.00	An ancillary building , at rear of the property lot, is in the flood zone	1886	T1_02_3.821		Right
		Ancillary	332 DAWSON ST	18	319405	5364111.1	0.05	0.08	0.00	Water through the lot, part of the ancillary building is in the flood zone	1886	T1_02_3.721		Left
		Ancillary	332 DAWSON ST	20	319413	5364087.4	0.12	0.28	0.03	Water through the lot, the ancillary building is in the flood zone	1886	T1_02_3.746		Both
		Driveway	332 DAWSON ST	19	319396	5363602.8	0.12	0.13	0.02	Culvert/Driveway is overtopped	1886	T1_02_3.742	C-036-T1_02	Both
		Driveway	48 CENTRE ST	17	319389	5363617.8	0.07	0.77	0.05	Culvert/Driveway is overtopped	1886	T1_02_3.718	C-035-T1_02	Left
		Bridge/Culvert	653 POLELINE RD	40	314758	5363421.7	0.26	1.42	0.37	Pedestrain bridge overtopped	1906	P_06_3.534	B-018-P_06	Both
		Road	202 WING RD	38	315141	5363535	0.25	0.86	0.22	A side road of a private property appears to be submerged	1907	P_06_3.005		Left
		Driveway	186 WING RD	35	315131	5363183.5	0.04	0.85	0.03	Part of the driveway appears to be submerged by flood water	1907	P_06_2.879	C-016-P_06	Both
		Lots	186 WING RD	36		5365141.2	0.71	0.32	0.23	Water through the lot, low areas are flooded, buildings are not in the flood zone	1907	P_06_2.886		Both
		Bridge/Culvert	NA	28	317425	5363535	0.13	1.35	0.18	Pedestrain bridge is overtopped	1909	T4_01_1.401	B-046-T4_01	Both
		Bridge/Culvert	394 FRASER RD	27	317366	5363183.5	0.13	0.41	0.05	Culvert/Driveway is overtopped	1909		C-045-T4_01	Both
		Driveway	459 POLELINE RD	30	316659	5363574.1	0.12	0.33	0.04	Culvert/Driveway is overtopped	1909	T5_01_1.41	C-050-T5_01	Both
		Driveway	174 WING RD	34		5363421.7	0.28	0.11	0.03	Driveway appears to be submerged by flood water	1932		C-015-P_06	Both
		Bridge/Culvert	589 POLELINE RD	33	315377	5364193.8	0.09	0.18	0.02	Culvert is overtopped	1932		C-014-P_06	Both
		Road	NA	26	316412	5360833.5	0.13	0.05	0.01	Culvert/Driveway is overtopped	1959	T3_02_1.372	C-044-T3_02	Both
		Driveway	221 VIBERT RD	23	319096	5365132.2	0.13	0.13	0.02	Culvert/Driveway is overtopped	1961	T2_01_0.484	C-038-T2_01	Left
		Road	VIBERT RD RAMP	7	319429	5361318.1	0.21	0.30	0.06	Road overtopped	1961	P_03_0.086		Both
		Road	VIBERT RD	9	319085	5363585.7	0.11	0.02	0.00	Vibiert Rd is overtopped	1986	P_02_1.289	C-011-P_02	Both

Critical Flood Criteria: >0.3m, >1.7 m/s, depth × velocity > 0.4 m²/s

Return	Flow at Confluence with Neebing River (m ³ /s)	Structure Type	Address	Structure ID	UŢM		Depth (m)	Velocity (m/s)	Depth × Velocity		Map Sheet	HEC-RAS Model Station	HEC-RAS Structure ID	
Period									(m²/s)	Comments				Bank
10 Year	19.01				320102	5360834	0.10	0.12	0.01	Culvert/Driveway is overtopped	331	T1_02_0.3441	C-029-T1_02	Both
		Bridge/Culvert	94 VIBERT RD	6	320165	320165 5365116		0.51	0.10	Culvert/Driveway is overtopped	353	P_01_11.129	B-009-P_01	Both
										Water through the lot, the ancillary building is in				
		Ancillary	332 DAWSON ST	20	319413	5364087	0.08	0.23	0.02	the flood zone	1886	T1_02_3.746		Both
		Driveway	332 DAWSON ST	19	319396	5363603	0.09	0.33	0.03	Culvert/Driveway is overtopped	1886	T1_02_3.742	C-036-T1_02	Both
		Driveway	48 CENTRE ST	17	319389	5363618	0.02	0.65	0.01	Culvert/Driveway is overtopped	1886	T1 02 3.718	C-035-T1 02	Left
		Bridge/Culvert	653 POLELINE RD	39	314758	4758 5363422 0		1.29	0.26	Pedestrain bridge overtopped		P 06 3.534	B-018-P 06	Both
										A side road of a private property appears to be			_	+
		Road	202 WING RD	37	315141	5363535	0.04	1.17	0.05	submerged	1907	P 06 3.005		Left
										Water through the lot, low areas are flooded,				
		Lots	186 WING RD	35	315157	5365141	0.39	0.37	0.15	buildings are not in the flood zone	1907	P 06 2.886		Both
		Bridge/Culvert	NA	27	317425	5363535	0.10	1.23	0.12	Pedestrain bridge is overtopped	1909	T4 01 1.401	B-046-T4 01	Both
		Bridge/Culvert	394 FRASER RD	26	317366	5363184	0.10	0.35	0.04	Culvert/Driveway is overtopped	1909	T4 01 1.009	C-045-T4 01	Both
		Driveway	459 POLELINE RD	29	316659	5363574	0.05	0.28	0.01	Culvert/Driveway is overtopped	1909	T5 01 1.41	C-050-T5 01	Both
										Driveway appears to be submerged by flood				
		Driveway	174 WING RD	33	315098	5363422	0.17	0.11	0.02	water	1932	P 06 2.751	C-015-P 06	Both
		Bridge/Culvert	589 POLELINE RD	32	315377	5364194	0.07	0.14	0.01	Culvert is overtopped	1932	P 06 2.31	C-014-P 06	Both
		Road	NA	25	316412	5360834	0.11	0.04	0.00	Culvert/Driveway is overtopped	1959	T3 02 1.372	C-044-T3 02	Both
		Driveway	221 VIBERT RD	23	319096	5365132	0.07	0.02	0.00	Culvert/Driveway is overtopped		T2 01 0.484	C-038-T2 01	Left
		Road	VIBERT RD S	9	319085	5363586	0.08	0.04	0.00	Vibiert Rd is overtopped	1986		C-011-P 02	Both

Critical Flood Criteria: >0.3m, >1.7 m/s, depth × velocity > 0.4 m²/s

Return Period	Confluence with Neebing River (m ³ /s)	Structure Type	Address	Structure ID	U	TM	Depth (m)	Velocity (m/s)	Depth × Velocity (m²/s)	Comments	Map Sheet	HEC-RAS Model Station	HEC-RAS Structure ID	Bank
5 Year	14.35	Bridge/Culvert	94 VIBERT RD	6	320165	5365116	0.03	0.62	0.02	Culvert/Driveway is overtopped	353	P_01_11.129	B-009-P_01	Both
		Bridge/Culvert	653 POLELINE RD	39	314758	5363422	0.15	0.73	0.11	Pedestrain bridge overtopped	1906	P_06_3.534	B-018-P_06	Both
										Water through the lot, low areas are flooded, buildings				
		Lots	186 WING RD	35	315157	5365141	0.08	0.53	0.04	are not in the flood zone	1907	P_06_2.886		Both
		Bridge/Culvert	NA	27	317425	5363535	0.07	0.45	0.03	Pedestrain bridge is overtopped	1909	T4_01_1.401	B-046-T4_01	Both
		Bridge/Culvert	394 FRASER RD	26	317366	5363184	0.07	0.40	0.03	Culvert/Driveway is overtopped	1909	T4_01_1.009	C-045-T4_01	Both
		Driveway	174 WING RD	33	315098	5363422	0.09	0.09	0.01	Driveway appears to be submerged by flood water	1932	P_06_2.751	C-015-P_06	Both
		Bridge/Culvert	589 POLELINE RD	32	315377	5364194	0.05	0.11	0.01	Culvert is overtopped	1932	P_06_2.31	C-014-P_06	Both
		Road	NA	25	316412	5360834	0.08	0.03	0.00	Culvert/Driveway is overtopped	1959	T3_02_1.372	C-044-T3_02	Both

Critical Flood Criteria: >0.3m, >1.7 m/s, depth × velocity > 0.4 m²/s

Return Period	Flow at Confluence with Neebing River (m ³ /s)		Address	Structure ID	UT	M	Depth (m)	Velocity (m/s)	Depth × Velocity (m²/s)	Comments	Map Sheet	HEC-RAS Model Station	HEC-RAS Structure ID	Bank
2 Year	8.16	Bridge/Culvert	653 POLELINE RD	39	314758	5363422	0.08	0.77	0.06	Pedestrain bridge overtopped	1906	P_06_3.534	B-018-P_06	Both
		Road	NA	25	316412	5360834	0.04	0.01	0.00	Culvert/Driveway is overtopped	1959	T3_02_1.372	C-044-T3_02	Both